

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403736899

Date Received:

03/30/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

WHITE, JEFFERY

jeffery.white@chevron.com

rbucogccinspectionreports@chevron.onmicrosoft.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708200952

Inspection Date: 02/29/2024

FIR Submit Date: 03/06/2024

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 327777

Location Name: BERNHARDT STATE PC N Number: 36-17 TANK County: _____

Qtrqtr: SENE Sec: 36 Twp: 5N Range: 67W Meridian: 6

Latitude: 40.357895 Longitude: -104.835130

FACILITY - API Number: 05-123-00 Facility ID: 327777

Facility Name: BERNHARDT STATE PC N Number: 36-17 TANK

Qtrqtr: SENE Sec: 36 Twp: 5N Range: 67W Meridian: 6

Latitude: 40.357895 Longitude: -104.835130

CORRECTIVE ACTIONS:

1 ☒ CA# 192694

Corrective Action: Anchor equipment ensuring anchors are engineered to ensure the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 607

Date: 04/07/2024

Response: CA COMPLETED

Date of Completion: 03/21/2024

Operator Comment: Complied Rule 607

ECMC Decision: Approved pending re-inspection

Date Run: 4/11/2024 Doc [#403736899]

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

2 ☒ CA# 192695

Corrective Action: Comply with Rule 606 and remove all debris.

Date: 03/14/2024

Response: CA COMPLETED

Date of Completion: 03/21/2024

Operator Comment: complied with Rule 606

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

3 ☒ CA# 192696

Corrective Action: Properly dispose of oily waste in accordance with Rule 905.e.

Date: 03/21/2024

Response: CA COMPLETED

Date of Completion: 03/21/2024

Operator Comment: Complied with Rule 95.e.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

4 ☒ CA# 192697

Corrective Action: Perform reclamation in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards.

Date: 04/30/2024

Response: CA COMPLETED

Date of Completion: 03/20/2024

Operator Comment: Complied with Rule 1003

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

5 ☒ CA# 192698

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 03/21/2024

Response: CA COMPLETED

Date of Completion: 03/21/2024

Operator Comment: Complied with Rule 1002.f.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Finished all corrective actions assigned to this site.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff White

Signed: _____

Title: HSE

Date: 3/30/2024 2:06:41 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403736899	FIR RESOLUTION SUBMITTED
403736907	photo
403736909	photo
403736910	photo
403736911	photo

Total Attach: 5 Files