

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403745535

Date Received:

04/08/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

FarmingtonRegulatoryTechs@hilcorp.com

Shorty, Priscilla

505-324-5188

pshorty@hilcorp.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000616

Inspection Date: 03/28/2024

FIR Submit Date: 04/01/2024

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326162

Location Name: UTE 32-11-N32N11W Number: 1NWNE County: _____

Qtrqtr: NWNE Sec: 1 Twp: 32N Range: 11W Meridian: N

Latitude: 37.050369 Longitude: -107.988831

FACILITY - API Number: 05-067- -00 Facility ID: 326162

Facility Name: UTE 32-11-N32N11W Number: 1NWNE

Qtrqtr: NWNE Sec: 1 Twp: 32N Range: 11W Meridian: N

Latitude: 37.050369 Longitude: -107.988831

CORRECTIVE ACTIONS:

1 ☒ CA# 193796

Corrective Action: Comply with rule 606, remove and properly dispose of debris.

Date: 04/08/2024

Response: CA COMPLETED

Date of Completion: 04/05/2024

Operator Comment: Removed wooden pallet and disposed of in trash.

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.
----------------------	--

2  CA# 193797

Corrective Action: Comply with rule 1002 Install or repair required BMPs.

Date: 04/08/2024

Response: CA COMPLETED

Date of Completion: 04/05/2024

Operator Comment:	Put materials down on rutted area and smoothed with tractor to stop rutting. Filled gully erosion and armored it with large stone material. See attached photos.
-------------------	--

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.
----------------------	--

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed:

Title: OperationsRegulatory Tech

Date: 4/8/2024 7:15:01 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403745535	FIR RESOLUTION SUBMITTED
403745537	UTE 32-11 101_714000616 Resolved Photos

Total Attach: 2 Files