

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403751057

Date Received:

04/11/2024

## FIR RESOLUTION FORM

Overall Status: CAC

### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

Walker, Mandi

mwalker@hilcorp.com

, General

FarmingtonRegulatoryTechs@hilcorp.com

Shorty, Priscilla

505-324-5188

pshorty@hilcorp.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 714000234

Inspection Date: 12/05/2023

FIR Submit Date: 12/28/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

### LOCATION - Location ID: 326426

Location Name: WILSON 34-9-N34N9W

Number: 29SENW

County: \_\_\_\_\_

Qtrqtr: SENW

Sec: 29

Twp: 34N

Range: 9W

Meridian: M

Latitude: 37.164697

Longitude: -107.852628

### FACILITY - API Number: 05-067-

-00

Facility ID: 326426

Facility Name: WILSON 34-9-N34N9W

Number: 29SENW

Qtrqtr: SENW

Sec: 29

Twp: 34N

Range: 9W

Meridian: M

Latitude: 37.164697

Longitude: -107.852628

### CORRECTIVE ACTIONS:

1 ☒ CA# 189639

Corrective Action: Comply with rule 606, remove and properly dispose of debris.

Date: 12/05/2023

Response: CA COMPLETED

Date of Completion: 04/10/2024

Operator  
Comment:

Removed tubing debris from location. See attached photos

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

2 ☒ CA# 189640

Corrective Action: Comply with rule 1003 f.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 04/10/2024

Operator Comment: Removed musk thistle on access road.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: \_\_\_\_\_

Title: OperationsRegulatory Tech

Date: 4/11/2024 1:37:09 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403751057	FIR RESOLUTION SUBMITTED
403751062	Wilson 34-9 29-1_71400034 Resolved Photos

Total Attach: 2 Files