

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403751135

Date Received:

04/11/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Walker, Mandi

mwalker@hilcorp.com

Shorty, Priscilla

505-324-5188

pshorty@hilcorp.com

^

FarmingtonRegulatoryTechs@hilcorp.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 714000533

Inspection Date: 03/06/2024

FIR Submit Date: 03/11/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON

State: TX

Zip: 77208

### LOCATION - Location ID: 333494

Location Name: ARGENTA 34-10-M34N10W

Number: 32NWSE

County: \_\_\_\_\_

Qtrqtr: NWSE

Sec: 32

Twp: 34N

Range: 10W

Meridian: M

Latitude: 37.144480

Longitude: -107.954750

### FACILITY - API Number: 05-067-

-00

Facility ID: 333494

Facility Name: ARGENTA 34-10-M34N10W

Number: 32NWSE

Qtrqtr: NWSE

Sec: 32

Twp: 34N

Range: 10W

Meridian: M

Latitude: 37.144480

Longitude: -107.954750

### CORRECTIVE ACTIONS:

1 ☒ CA# 192921

Corrective Action: Maintain secondary containment per rule 603.

Date: 04/10/2024

Response: CA COMPLETED

Date of Completion: 04/10/2024

Operator  
Comment:

See attached photos

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

2 ☒ CA# 192922

Corrective Action: Comply with Rule 1002.f. Install or repair required BMPs.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 04/10/2024

Operator Comment: Resolved through FIRR 714000138. See attached photos

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: \_\_\_\_\_

Title: OperationsRegulatory Tech

Date: 4/11/2024 2:00:32 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403751135	FIR RESOLUTION SUBMITTED
403751139	ARGENTA 34-10 32-2_714000138_714000533_Resolved Photos

Total Attach: 2 Files