

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403755437

Date Received:  
04/16/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10663

Name of Operator: ENDURING RESOURCES LLC

Address: 6300 S SYRACUSE WAY, SUITE 525

City: CENTENNIAL State: CO Zip: 80111

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Walter, Kyle

kwalter@enduringresources.com

Huntington, Heather

hhuntington@enduringresources.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 714000571

Inspection Date: 03/19/2024

FIR Submit Date: 03/20/2024

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: ENDURING RESOURCES LLC

Company Number: 10663

Address: 6300 S SYRACUSE WAY, SUITE 525

City: CENTENNIAL State: CO Zip: 80111

#### LOCATION - Location ID: 326276

Location Name: CRADER-N34N9W Number: 3SWSE County: \_\_\_\_\_

Qtrqtr: SWSE Sec: 3 Twp: 34N Range: 9W Meridian: N

Latitude: 37.232296 Longitude: -107.838838

#### FACILITY - API Number: 05-067- -00 Facility ID: 326276

Facility Name: CRADER-N34N9W Number: 3SWSE

Qtrqtr: SWSE Sec: 3 Twp: 34N Range: 9W Meridian: N

Latitude: 37.232296 Longitude: -107.838838

### CORRECTIVE ACTIONS:

1 CA# 193377

Corrective Action: Comply with rule 606. Remove and properly store unused equipment.

Date: 04/04/2024

Response: CA COMPLETED

Date of Completion: 04/15/2024

Operator  
Comment:

PHOTOS ATTACHED OF CORRECTIVE ACTION COMPLETED

ECMC Decision: \_\_\_\_\_

	ECMC Representative:		
--	----------------------	--	--

2

CA# 193378

Corrective Action: 

Comply with rule 606, remove and properly dispose of debris.

Date: 03/27/2024

Response: CA COMPLETED

Date of Completion: 04/16/2024

Operator Comment:

PHOTOS ATTACHED OF CORRECTIVE ACTION COMPLETED

ECMC Decision:

ECMC Representative:

3

CA# 193379

Corrective Action: 

Erosion controls need to be installed and maintained until bare soils are stabilized with desirable perennial vegetation. Comply with rule 1002 Install or repair required BMPs.

Date: 03/27/2024

Response: CA COMPLETED

Date of Completion: 04/15/2024

Operator Comment:

PHOTOS ATTACHED OF THE CORRECTIVE ACTION COMPLETED

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Heather Huntington

Signed: \_\_\_\_\_

Title: Permitting Tech

Date: 4/16/2024 9:25:52 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403755533	CA PHOTOS

Total Attach: 1 Files