



FORM  
17  
Rev  
11/20

State of Colorado  
Energy & Carbon Management Commission  
1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403755733

BRADENHEAD TEST REPORT

Step 1. Before opening any valves, record all tubing and casing pressures as found.  
Step 2. Collect liquid and gas samples as required; consult Bradenhead Testing and Reporting Instructions and Guidance for field specific Orders at <http://ecmc/reg.html#/opguidance>  
Step 3. Conduct Bradenhead test.  
Step 4. Submit Form 17 within 10 days of test. Attach a wellbore diagram if not previously submitted or if wellbore configuration has changed since last wellbore diagram was submitted.  
Step 5. Submit sample analytical results via Form 43.

1. ECMC Operator Number: 1003223. BLM Lease No:

2. Name of Operator: NOBLE ENERGY INC

4. API Number; 05-123-48905-005. Multiple completion? Yes No

6. Well Name: BorysNumber: C22-775

7. Location (QtrQtr, Sec, Twp, Rng, Meridian): SENW,22,4N,64W,6

8. County WELD9. Field Name: WATTENBERG

10. Minerals: Fee State Federal Indian

11. Date of Test: 04/10/2024

12. Well Status: 

Flowing

Shut In Gas Lift

Pumping Injection

Clock/Intermitter

Plunger Lift

13. Number of Casing Strings: 

Two Three Liner?

14. EXISTING PRESSURES

Record all pressures as found	Tubing: 0 Fm:	Tubing: Fm:	Prod Csg 0 Fm:	Intermediate Csg:	Surf. Csg 0
-------------------------------	------------------	----------------	-------------------	----------------------	----------------

BRADENHEAD TEST

With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (Bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals.  
Describe character of flow in "Bradenhead Flow" column: O = No Flow; C = Continuous; D = Down to 0; S = Surge; W = Whisper  
Describe fluid type in "Bradenhead Fluid" column: H = Water H2O; M = Mud; G = Gas; V = Vapor; L = Liquid Hydrocarbon; H & M = Water & Mud; H & G = Water & Gas; H & V = Water & Vapor; M & G = Mud & Gas; M & V = Mud & Vapor; G & V = Gas & Vapor; H & L = Water & Liquid Hydrocarbon; M & L = Mud & Liquid Hydrocarbon; G & L = Gas & Liquid Hydrocarbon; V & L = Vapor & Liquid Hydrocarbon; N = None

Buried valve? Yes No	Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermedia Csg PSIG	Bradenhead Flow:	Bradenhead Fluid:
Confirmed open? Yes No	00:00	0		0		NO FLOW	NONE
BRADENHEAD SAMPLE TAKEN? Yes No Gas Liquid	05:00	0		0		NO FLOW	NONE
Character of Bradenhead fluid: Clear Fresh Sulfur Salty Black Other:(describe)	10:00	0		0		NO FLOW	NONE
	15:00	0		0		NO FLOW	NONE
	20:00	0		0		NO FLOW	NONE
	25:00	0		0		NO FLOW	NONE
	30:00	0		0		NO FLOW	NONE
REQUIRED - Instantaneous Bradenhead Pressure at End of Test: 0 PSIG							

Date Run: 4/16/2024 Doc [#403755733]

Page 1 of 2

## INTERMEDIATE CASING TEST

With gauges monitoring production, intermediate casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals.

Describe character of flow in "Intermediate Flow" column: O = No Flow; C = Continuous; D = Down to 0; S = Surge; W = Whisper

Describe fluid type in "Intermediate Fluid" column: H = Water H<sub>2</sub>O; M = Mud; G = Gas; V = Vapor; L = Liquid Hydrocarbon; H & M = Water & Mud; H & G = Water & Gas; H & V = Water & Vapor; M & G = Mud & Gas; M & V = Mud & Vapor; G & V = Gas & Vapor; H & L = Water & Liquid Hydrocarbon; M & L = Mud & Liquid Hydrocarbon; G & L = Gas & Liquid Hydrocarbon; V & L = Vapor & Liquid Hydrocarbon; N = None.

Buried valve? <input type="checkbox"/> Yes <input type="checkbox"/> No	Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermediate Csg PSIG	Intermediate Flow:	Intermediate Fluid:
Confirmed open? <input type="checkbox"/> Yes <input type="checkbox"/> No	00:00						
INTERMEDIATE SAMPLE TAKEN? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid	05:00						
	10:00						
	15:00						
Character of Intermediate fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black Other:(describe) _____	20:00						
	25:00						
	30:00						
	REQUIRED - Instantaneous Intermediate Casing Pressure at End of Test: _____ PSIG						

Comments: NO PRESSURE ON SURFACE CASING. PRODUCTION CASING ZERO. UNABLE TO TAKE TUBING PRESSURE DUE TO FRAC VALVE.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed By: <u>d mann</u>	Title: _____	Phone: ( ) _____
Signed: <u>evan varnas</u>	Title: <u>regulatory analyst</u>	Date: <u>4/16/2024</u>
Witnessed By: _____	Title: _____	Agency: _____