

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403758857

Date Received:
04/17/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10663

Name of Operator: ENDURING RESOURCES LLC

Address: 6300 S SYRACUSE WAY, SUITE 525

City: CENTENNIAL State: CO Zip: 80111

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Huntington, Heather

hhuntington@enduringresources.com

Walter, Kyle

kwalter@enduringresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000571

Inspection Date: 03/19/2024

FIR Submit Date: 03/20/2024

FIR Status: _____

Inspected Operator Information:

Company Name: ENDURING RESOURCES LLC

Company Number: 10663

Address: 6300 S SYRACUSE WAY, SUITE 525

City: CENTENNIAL State: CO Zip: 80111

LOCATION - Location ID: 326276

Location Name: CRADER-N34N9W Number: 3SWSE County: _____

Qtrqtr: SWSE Sec: 3 Twp: 34N Range: 9W Meridian: N

Latitude: 37.232296 Longitude: -107.838838

FACILITY - API Number: 05-067- -00 Facility ID: 326276

Facility Name: CRADER-N34N9W Number: 3SWSE

Qtrqtr: SWSE Sec: 3 Twp: 34N Range: 9W Meridian: N

Latitude: 37.232296 Longitude: -107.838838

CORRECTIVE ACTIONS:

1 CA# 193377

Corrective Action: Comply with rule 606. Remove and properly store unused equipment.

Date: 04/04/2024

Response: CA COMPLETED

Date of Completion: 04/15/2024

Operator
Comment:

PHOTOS ATTACHED OF CORRECTIVE ACTION COMPLETED

ECMC Decision: _____

ECMC Representative:			
----------------------	--	--	--

2	CA# 193378		
Corrective Action:		Comply with rule 606, remove and properly dispose of debris.	Date: 03/27/2024
Response:		CA COMPLETED	Date of Completion: 04/15/2024
Operator Comment:		PHOTOS ATTACHED OF CORRECTIVE ACTION COMPLETED	
ECMC Decision: _____			
ECMC Representative:			

3	CA# 193379		
Corrective Action:		Erosion controls need to be installed and maintained until bare soils are stabilized with desirable perennial vegetation. Comply with rule 1002 Install or repair required BMPs.	Date: 03/27/2024
Response:		CA COMPLETED	Date of Completion: 04/15/2024
Operator Comment:		PHOTOS ATTACHED OF THE CORRECTIVE ACTION COMPLETED	
ECMC Decision: _____			
ECMC Representative:			

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	Correct photos have been uploaded
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Heather Huntington	Signed: _____
Title: Permitting Tech	Date: 4/17/2024 3:58:43 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403758861	CA PHOTOS

Total Attach: 1 Files