

State of Colorado
Energy & Carbon Management Commission



Document Number:
403759605

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:
04/18/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Tammy Jones</u>		<u>tajones@hilcorp.com</u>
<u>Priscilla Shorty</u>		<u>pshorty@hilcorp.com</u>
		<u>jennifer.a.dixon@conocophillips.com</u>
		<u>sam.widmer@cop.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000137
Inspection Date: 11/16/2023 FIR Submit Date: 11/29/2023 FIR Status:

Inspected Operator Information:

Company Name: CONOCO PHILLIPS COMPANY Company Number: 19160
Address: 925 N ELDRIDGE PARKWAY
City: HOUSTON State: TX Zip: 77079

LOCATION - Location ID: 385889

Location Name: ARGENTA 34-10-M34N10W Number: 31SENW County:
Qtrqtr: SENW Sec: 31 Twp: 34N Range: 10W Meridian: M
Latitude: 37.147067 Longitude: -107.974791

FACILITY - API Number: 05-067-00 Facility ID: 385889

Facility Name: ARGENTA 34-10-M34N10W Number: 31SENW
Qtrqtr: SENW Sec: 31 Twp: 34N Range: 10W Meridian: M
Latitude: 37.147067 Longitude: -107.974791

CORRECTIVE ACTIONS:

1 CA# 188634

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: 11/16/2023

Response: CA COMPLETED

Date of Completion: 04/17/2021

Operator Comment: See attached photos showing seeding and mulching.

ECMC Decision:

ECMC Representative:

2 CA# 188635

Corrective Action: Comply with Rule 1002.f. Install or repair required BMPs per Rule 1002.f. BMP's shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to rule 1004.

Date:

Response: CA COMPLETED

Date of Completion: 04/17/2024

Operator Comment: See attached photos showing resolution to the rills.

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed:

Title: OperationsRegulatory Tech

Date: 4/18/2024 10:02:56 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (http://ecmcweblink.state.co.us/) - Search by Document Number.

Table with 2 columns: Document Number, Description. Rows include 403759622 (Argenta 34-10 #31-1 Photo Log) and 403759629 (Argenta 34-10 #31-1 Site Map).

Total Attach: 2 Files