

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403764008

Date Received:

04/22/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

8 of 8 CAs from the FIR responded to on this Form

8 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10701

Name of Operator: UPLAND EXPLORATION LLC

Address: 424 S MAIN ST

City: BOERNE State: TX Zip: 78006

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Trujillo, Aaron

aaron.trujillo@state.co.us

+

dnr_cogccenforcement@state.co.us

Allison, Rick

rick.allison@state.co.us

Rollins, Dustin

dustin@uplandexploration.com

dustin@uplandexploration.com

david@uplandexploration.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 697504537

Inspection Date: 02/28/2023

FIR Submit Date: 03/06/2023

FIR Status: _____

Inspected Operator Information:

Company Name: UPLAND EXPLORATION LLC

Company Number: 10701

Address: 424 S MAIN ST

City: BOERNE State: TX Zip: 78006

LOCATION - Location ID: 456651

Location Name: Salt Ranch Fee Number: 18 East County: _____

Qtrqtr: SESE Sec: 18 Twp: 11N Range: 64W Meridian: 6

Latitude: 40.914603 Longitude: -104.584484

FACILITY - API Number: 05-123-00 Facility ID: 456651

Facility Name: Salt Ranch Fee Number: 18 East

Qtrqtr: SESE Sec: 18 Twp: 11N Range: 64W Meridian: 6

Latitude: 40.914603 Longitude: -104.584484

CORRECTIVE ACTIONS:

1 CA# 167869

Corrective Action: Comply with Rule 606.c.

Date: 02/10/2023

The corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/04/2023

Operator Comment: Location was all sprayed last year by CCR before Upland took over the lease, weeds were dormant, this was discussed with Chris Binschus 2/28/2023. Crews conducted pulling weeds by hand (3/2/23 - 3/31/23); Precision Industrial Applications is conducting weed spraying at the location and along lease road .Upland has continued to spray and remove weeds. Colorado had seen an unprecedented amount of precipitation. Russian Thistle was present along the road and adjacent lands prior to Upland operations as represented in historical aerial photos. Weed mitigation/spraying and removal is ongoing. Weed Management Plan was approved per Inspection Document #697504884.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 167870

Corrective Action: Comply with Rule 606.d.

Date: 02/10/2023

The corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 02/10/2023

Operator Comment: Upland placed an enclosed dumpster on location - trash being discovered is not a direct result of Upland operations; field personnel are maintaining good housekeeping measures. The access road is utilized by multiple contractors and the landowner. The location and access road is driven and maintained daily, if trash is observed it is picked up and properly disposed of; this area experiences significant winds; trash observed by the inspector is not the result of Upland activities. Operator continues to work with Subcontractors to keep trash properly picked up.

ECMC Decision: _____

ECMC Representative: _____

3 CA# 167871

Corrective Action: Comply with Rule 427.b.

Date: 02/28/2023

The corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 06/27/2023

Operator Comment: Upland has reduced the speed of the road, adjusted the schedule of water hauling activities to the evening and on non-high wind days, utilizing water trucks to the road as needed, and applied road base, graded, compacted to an additional 1.9 miles of the access road from 6/19-6/27/23. As represented in several FIRR responses and directly in meetings with ECMC, dust mitigation and stormwater management is an ongoing activity due to weather events and winds, Colorado has seen an unprecedented amount of precipitation. The balance of watering and grading is being completed as necessary.

ECMC Decision: _____

ECMC Representative: _____

4 CA# 167872

Corrective Action: Comply with Rule 912.a. and 912.b. to submit a Form 19 immediately for spills around the frac tanks.

Date: 02/10/2023

Response: CA COMPLETED

Date of Completion: 02/10/2023

Operator Comment: FIRR 403414217 approved CA pending re-inspection. Non-reportable spill to either ECMC or CDPHE; Material spilled was hydraulic fluid less than 3 gallons. Manifests attached to FIRR 403414217.

ECMC Decision: _____

ECMC
Representative:

5 CA# 167873

Corrective Action: Comply with Rule 913.c.(8). to submit a Form 27 for the pit.

Date: 02/10/2023

Response: CA COMPLETED

Date of Completion: 11/14/2023

Operator
Comment:

Remediation Project #32199 has received a "No Further Action" under Form 27 Document #403588182.

ECMC Decision:

ECMC
Representative:

6 CA# 167874

Corrective Action: Comply with Rule 1002.c.

Date: 02/10/2023

The corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 08/07/2023

Operator
Comment:

Per Inspection Document #697504785, ECMC acknowledges that "Operator has reseeded the topsoil stockpile since the previous inspection". Topsoil stockpiles have been sprayed and reseeded as well as crimped and stabilized to address the excessive rainfall and wind storm events; Upland continues to conduct weed and sediment erosion mitigation as necessary along the topsoil stockpiles and along the access road. Inspection Document 697504884 acknowledges the proper weed management plan is in place.

ECMC Decision:

ECMC
Representative:

7 CA# 167875

Corrective Action: Comply with Rule 1002.e.(1) and 1002.e.(4)

Date: 02/10/2023

The corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 02/10/2023

Operator
Comment:

Upland is maintaining its SW BMPs at the location to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Ongoing maintenance of SW controls has been being maintained and sediment controls, rock checks and/or waddles have been routinely replaced. Stormwater controls will be managed and maintain until the location is fully reclaimed. FIRR Document #403572538 stated that this CA was approved pending re-inspection. SW BMPs were addressed at the location, access road and Geary Creek areas see attached photos. FIRR Document #403533083 says CA was approved pending re-inspection. Operator is maintaining proper weed management per approved plan. Operator is working with contractor for topsoil sampling and reclamation of disturbed areas along the access road and other areas identified.

ECMC Decision:

ECMC
Representative:

8 CA# 167876

Corrective Action: Comply with Rules 1002.f.(2) and 1002.f.(2)B

Date: 02/10/2023

The corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 02/10/2023

Upland is maintaining its SW BMPs at the location to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Ongoing maintenance of SW controls has been being

Operator Comment:	maintained and sediment controls, rock checks and/or waddles have been routinely replaced. Stormwater controls will be managed and maintain until the location is fully reclaimed. FIRR Document #403572538 stated that this CA was approved pending re-inspection. SW BMPS were addressed at the location, access road and Geary Creek areas see attached photos. FIRR Document #403533083 says CA was approved pending re-inspection. Operator has cleaned up and properly contained gasoline containers. Porta-john has been up righted and stabilized.
ECMC Decision:	
ECMC Representative:	

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dustin Rollins Signed: _____

Title: Field Supervisor Date: 4/22/2024 2:30:15 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files