

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/22/2024

Submitted Date:

04/22/2024

Document Number:

702502635

FIELD INSPECTION FORM

Loc ID: 315629 Inspector Name: Burchett, Kirby On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 21 Number of Comments
 14 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 10384
 Name of Operator: GENESIS GAS & OIL COLORADO LLC
 Address: 1141 NORTH LOOP 1604 E 105-414
 City: SAN ANTONIO State: TX Zip: 78232

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Karcz, Jeffrey	(303) 909-6401	jkarcz@genesigoco.com	
Vogt, Molly	(303) 249-1355	mvogt@genesigoco.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231192	WELL	SI	08/01/2023	OW	103-08861	MOORE 1-12 MH	SI

General Comment:

[ECMC Inspection Report Summary](#)

On Monday, 04/22/2024, Inspector Kirby Burchett, conducted a follow up field inspection at Genesis Gas & Oil Colorado LLC on the Moore 4-11 MH well, Location #315702, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Inspection #702501526 on 6/22/23, Inspection #702501840 on 9/11/23 and Inspection #702502635 on 10/11/23.

The following Corrective Actions have not been resolved and original due dates will remain:

1. Debris. Including last years weeds.
2. Stained soils. Multiple spills around tank battery and wellhead.
3. Inadequate wildlife protection.
4. Tank labels missing required information.
5. Bradenhead not accessible or visible.
6. Unmarked anchor.
7. Chemical storage. Damaged labels.
8. No location entrance sign.

Refer to Inspection Photos for observed compliance issues.

While there during normal operations the following compliance issue was observed:

1. No monthly operations reports since September 2023.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Location is behind private gate. No location entrance sign.		
Corrective Action:	The Location Entrance sign will identify: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available).	Date:	10/12/2023
Type	CONTAINERS		
Comment:	Unmarked pails inside containment at tank battery.		
Corrective Action:	Containers that are used to store, treat, or otherwise handle a hazardous material and which are required to be marked, placarded, or labeled in accordance with the U.S. Department of Transportation's Hazardous Materials Regulations, will retain the markings, placards, and labels on the Container. Such markings, placards, and labels will be retained on the Container until it is sufficiently cleaned of residue and purged of vapors to remove any potential hazards.	Date:	07/03/2023
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Production tanks missing required information		
Corrective Action:	All Tanks with a capacity of 10 Barrels or greater will be labeled or posted with the following information: Name of Operator; Operator's emergency contact telephone number; Tank capacity; Tank contents; and NFPA label or equivalent globally harmonized label.	Date:	07/03/2023
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	505-259-9605 or 911		
Corrective Action:		Date:	

Good Housekeeping:			
Type			
Comment:	Unused equipment and supplies being stored on location		
Corrective Action:	The storage, placement, or maintenance of equipment, vehicles, trailers, commercial products, chemicals, drums, totes, containers, materials, and all other supplies not necessary for use on an Oil and Gas Locations is prohibited.	Date:	06/30/2023
Type	WEEDS		
Comment:	Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.		
Corrective Action:		Date:	
Type	WEEDS		
Comment:			

Corrective Action:		Date:	
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	All trash, rubbish, and other waste material will be properly contained until removed from the Oil and Gas Location. At no time will trash, debris, or rubbish be placed or remain on the ground.	Date:	06/30/2023

Overall Good:

Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	Stained soil all around wellhead		
Corrective Action:	Remove and properly dispose of oily waste and impacted soil.		Date: 07/08/2023
Crude Oil	Tank	<= 1 bbl	
Comment:	Several spills around 3 crude oil production tanks		
Corrective Action:	Remove and properly dispose of oily waste and impacted soil.		Date: 07/08/2023
Crude Oil	Truck Loadout	<= 1 bbl	
Comment:	Leaking valve and puddle of oil on the ground		
Corrective Action:	Remove and properly dispose of oily waste and impacted soil.		Date: 07/08/2023
Crude Oil		<= 1 bbl	
Comment:	Soil staining inside production pit.		
Corrective Action:	Remove and properly dispose of oily waste and impacted soil.		Date: 07/08/2023

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type			
Type	TANK BATTERY		
Comment:	Livestock fence and barbed wire		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Pumping unit and wellhead. Double rail square tubing		
Corrective Action:			Date:

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Open top tank with hazardous material storage open to wildlife		
Corrective Action:	All open-topped Tanks will be equipped with screens or other appropriate equipment to prevent entry by wildlife, including birds and bats		Date: 07/03/2023
Type: Deadman # & Marked	# 4		

Comment:	1 unmarked		
Corrective Action:	All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.	Date:	06/29/2023
Type:	Bradenhead	#	0
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow Bradenhead visual inspection.	Date:	07/03/2023

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	100 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined			
Corrective Action:				
				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 231192 Type: WELL API Number: 103-08861 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last Production Reported - July 2023
September 2023 Proction Report
Review of production records indicate operator is delinquent in submitting monthly operations reports.

Corrective Action: **Submit required Form 7(s), Operator's Monthly Report of Operations.** Date: 05/23/2024

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Stormwater BMPs need implementation and maintenance.](#)

Corrective Action: [Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.](#)

Date: 07/08/2023

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: 117345 Lat: 40.075602 Long: -107.780352

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: [Unlined](#)

Corrective Action

Date:

Fencing:

Fencing Type: Livestock Fencing Condition: _____

Comment:

Corrective Action

Date:

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date:

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702502636	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6519930