

Inspection Photos

04/19/2024

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335936

Inspection Doc: 696205769

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335936



Photo 1: Photo taken from the east end of the Location, facing southwest and west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335936



Photo 2: Signs at wells in disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335936



Photo 3: Photos 3-4 shows signage at tanks on Location does not comport with 605 requirements. Labels on tanks have torn, or information (Operator Name, Capacity, Etc...) is incorrect , or missing.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335936



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335936



Photo 5: Photo example showing lines at tanks missing required cap/plug.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335936



Photo 6: Fence in disrepair at wells, tank battery and separators.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335936



Photo 7: Fence in disrepair at wells, tank battery and separators.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335936



Photo 8: Photo left example showing areas that appear to be progressing towards 1003 standards. Photo right example of areas where additional revegetation efforts may be necessary to ensure uniform establishment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources