

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403758857

Date Received:
04/17/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Huntington, Heather</u>		<u>hhuntington@enduringresources.com</u>
<u>Walter, Kyle</u>		<u>kwalter@enduringresources.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000571
Inspection Date: 03/19/2024 FIR Submit Date: 03/20/2024 FIR Status: _____

Inspected Operator Information:

Company Name: ENDURING RESOURCES LLC Company Number: 10663
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

LOCATION - Location ID: 326276

Location Name: CRADER-N34N9W Number: 3SWSE County: _____
Qtrqtr: SWSE Sec: 3 Twp: 34N Range: 9W Meridian: N
Latitude: 37.232296 Longitude: -107.838838

FACILITY - API Number: 05-067-00 Facility ID: 326276

Facility Name: CRADER-N34N9W Number: 3SWSE
Qtrqtr: SWSE Sec: 3 Twp: 34N Range: 9W Meridian: N
Latitude: 37.232296 Longitude: -107.838838

CORRECTIVE ACTIONS:

1 CA# 193377

Corrective Action: Comply with rule 606. Remove and properly store unused equipment. Date: 04/04/2024

Response: CA COMPLETED Date of Completion: 04/15/2024

Operator Comment: PHOTOS ATTACHED OF CORRECTIVE ACTION COMPLETED

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

2 CA# 193378

Corrective Action: Comply with rule 606, remove and properly dispose of debris.

Date: 03/27/2024

Response: CA COMPLETED

Date of Completion: 04/15/2024

Operator Comment: PHOTOS ATTACHED OF CORRECTIVE ACTION COMPLETED

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

3 CA# 193379

Corrective Action: Erosion controls need to be installed and maintained until bare soils are stabilized with desirable perennial vegetation. Comply with rule 1002 Install or repair required BMPs.

Date: 03/27/2024

Response: CA COMPLETED

Date of Completion: 04/15/2024

Operator Comment: PHOTOS ATTACHED OF THE CORRECTIVE ACTION COMPLETED

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment: Correct photos have been uploaded

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Heather Huntington

Signed: _____

Title: Permitting Tech

Date: 4/17/2024 3:58:43 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403758857	FIR RESOLUTION SUBMITTED
403758861	CA PHOTOS

Total Attach: 2 Files