

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403759605

Date Received:

04/18/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Tammy Jones</u>		<u>tajones@hilcorp.com</u>
<u>Priscilla Shorty</u>		<u>pshorty@hilcorp.com</u>
		<u>jennifer.a.dixon@conocophillips.com</u>
		<u>sam.widmer@cop.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000137

Inspection Date: 11/16/2023

FIR Submit Date: 11/29/2023

FIR Status: _____

Inspected Operator Information:

Company Name: CONOCO PHILLIPS COMPANY Company Number: 19160
Address: 925 N ELDRIDGE PARKWAY
City: HOUSTON State: TX Zip: 77079

LOCATION - Location ID: 385889

Location Name: ARGENTA 34-10-M34N10W Number: 31SENW County: _____
Qtrqr: SENW Sec: 31 Twp: 34N Range: 10W Meridian: M
Latitude: 37.147067 Longitude: -107.974791

FACILITY - API Number: 05-067-00 Facility ID: 385889

Facility Name: ARGENTA 34-10-M34N10W Number: 31SENW
Qtrqr: SENW Sec: 31 Twp: 34N Range: 10W Meridian: M
Latitude: 37.147067 Longitude: -107.974791

CORRECTIVE ACTIONS:

1 ☒ CA# 188634

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: 11/16/2023

Response: CA COMPLETED

Date of Completion: 04/17/2021

Operator Comment: See attached photos showing seeding and mulching.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

2 ☒ CA# 188635

Corrective Action: Comply with Rule 1002.f. Install or repair required BMPs per Rule 1002.f. BMP's shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to rule 1004.

Date: _____

Response: CA COMPLETED

Date of Completion: 04/17/2024

Operator Comment: See attached photos showing resolution to the rills.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 4/18/2024 10:02:56 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403759605	FIR RESOLUTION SUBMITTED
403759622	Argenta 34-10 #31-1 Photo Log
403759629	Argenta 34-10 #31-1 Site Map

Total Attach: 3 Files