

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/22/2024

Submitted Date:

04/24/2024

Document Number:

713600975

FIELD INSPECTION FORM

Loc ID 484358 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10797
Name of Operator: DESERT EAGLE OPERATING LLC
Address: 17101 PRESTON RD SUITE 105
City: DALLAS State: TX Zip: 75248

Findings:

- 8 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Bulf, Cathy		cathybulf@gmail.com	
Butler, Brad	972-345-9195	butleroil@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
484677	WELL	PR	11/28/2023	OW	071-09931	Red Rocks 1-16	RI

General Comment:

This is a follow up of the previous reclamation inspection #713600421.
See attached photos and additional details within this report.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Good Housekeeping:

Type	OTHER		
Comment:	There are no wildlife protections such as bird netting at the chemical fuel containers that have leaked into the secondary containment.		
Corrective Action:	Comply with Rule 902.b. Install or repair wildlife protection equipment.	Date:	05/01/2024
Type	DEBRIS		
Comment:	There is tree debris along the flowline and at the location that needs to be removed. Previous corrective action was not completed.		
Corrective Action:	Comply with Rule 606.	Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING Pass

Comment Fence panel are around equipment.

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS Fail

Comment Topsoil was not salvaged along the flowline which is greater than 8". Topsoil was not protected from compaction or contamination at the location. There was no topsoil salvage along the new access road and vehicle traffic has heavily compacted the soils. Topsoil will likely need to be imported to the location or require soil amendments for reclamation.

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? Fail

Comment There is still drill cutting waste that needs to be cleaned up at the north side of the location.

Corrective Action Comply with 1003.a. and Rule 905. Date 05/01/2024

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? **Fail** _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment The location has been seeded however there are areas of compacted soils. Soils were not properly decompacted. Areas of soil compaction will need to be decompacted by cross ripping to at least 18inches to establish vegetation. A follow up inspection will be performed later in the growing season.

Corrective Action Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	

Comment: There are multiple areas of stained soils around the engine compressor that must be cleaned up. There are oily fluids in the engine skid and inside secondary containment.

Corrective Action: Comply with 1002.f.(2).B.D Conduct maintenance on equipment, cleanup stained material, and review self inspection processes.

Date: 04/26/2024

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600976	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6522265