

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403766626

Date Received:

04/23/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Tyranny Bergin

Phone

970-313-5547

Email

EHSCOGCCInspections@pdce.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 701900930

Inspection Date: 06/02/2023

FIR Submit Date: 06/26/2023

FIR Status: _____

Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 322959

Location Name: BROWN-64N67W Number: 20SWNW County: _____

Qtrqtr: SWN Sec: 20 Twp: 4N Range: 67W Meridian: 6
W

Latitude: 40.300440 Longitude: -104.919860

FACILITY - API Number: 05-123- -00 Facility ID: 322959

Facility Name: BROWN-64N67W Number: 20SWNW

Qtrqtr: SWN Sec: 20 Twp: 4N Range: 67W Meridian: 6
W

Latitude: 40.300440 Longitude: -104.919860

CORRECTIVE ACTIONS:

1 ☒ CA# 173849

Corrective Action: Comply with Rule 1002.f. Install or repair required BMPs per Rule 1002.f. BMP's shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to rule 1004.

Date: 06/02/2023

The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 04/19/2024

Operator Comment: Disced, seeded and straw crimped. The erosion issue on the southwest side of the site has been mitigated and filled in on our site and the farmer fixed his ditch on the edge of our site so that no water should be flowing through our pad moving forward. CA complete.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment: Disced, seeded and straw crimped. The erosion issue on the southwest side of the site has been mitigated and filled in on our site and the farmer fixed his ditch on the edge of our site so that no water should be flowing through our pad moving forward. CA complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyranny Bergin

Signed: _____

Title: H&S Specialist-Operations

Date: 4/23/2024 2:59:53 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403766626	FIR RESOLUTION SUBMITTED
403766643	Brown 1
403766651	Brown 2
403766658	Brown 3
403766662	Brown 4

Total Attach: 5 Files