

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2024

Submitted Date:

04/18/2024

Document Number:

697505258

FIELD INSPECTION FORM

Loc ID 460656 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10373
Name of Operator: NGL WATER SOLUTIONS DJ LLC
Address: 865 NORTH ALBION ST., STE 400
City: DENVER State: CO Zip: 80220

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		joseph.vargo@nglep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
460656	LOCATION	AC			-	ROY SWD FACILITY	RI

General Comment:

This is a follow up Interim Reclamation and Stormwater Inspection to FIR Doc.# 697504857.

Inspected Facilities

Facility ID: 460656 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: DRY LAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ In Process _____

Comment **Operator has performed interim reclamation activities and the remaining topsoil stockpile has been reseeded.**
Per Rule 1002.c., BMPs to prevent weed establishment and to maintain soil microbial activity shall be implemented and maintained.

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____ Fail _____

Comment **Vehicle traffic was observed along a portion of the northwestern interim reclamation area damaging reclamation. Operator will be responsible for reclaiming any areas that do not establish. Refer to Photo 1.**

Corrective Action **Operator shall implement BMPs to comply with Rule 1002.e.(4) to restrict lease access to lease roads and the working pad surface.**

Date **05/16/2024**

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403760386	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6515168
697505259	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6515167