

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: State SW 3-16H

Loc ID: 433168

Inspection: 694100298



Exhibit A



Exhibit B



Exhibit C

CA: Soil/gravel stockpile unlined and no BMPs (wattles) in place to prevent offsite runoff after or during a precipitation event. Install or repair required BMPs per Rule 1002.f.(2) Control, Date manage, and prevent weedy, annual vegetation on all topsoil stockpiles. If reseeding is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted.

CA Resolution: Operator has reported that the identified stockpile has been removed. Materials were used to repair areas onsite that were showing minor erosion. Location is now in compliance with Rule 1002.f.(2).