


FORM 6 Rev 11/20	State of Colorado Energy & Carbon Management Commission				<table><tr><td>DE</td><td>ET</td><td>OE</td><td>ES</td></tr></table>				DE	ET	OE	ES																																																		
	DE	ET	OE	ES																																																										
1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109				Document Number: 403769650 Date Received:																																																										
WELL ABANDONMENT REPORT																																																														
<p>This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.</p>																																																														
ECMC Operator Number: 100322				Contact Name: Maryam Akbari																																																										
Name of Operator: NOBLE ENERGY INC				Phone: (661) 633-4604																																																										
Address: 1099 18TH STREET SUITE 1500				Fax:																																																										
City: DENVER State: CO Zip: 80202				Email: maryamakbari@chevron.com																																																										
For "Intent" 24 hour notice required,				Name: Evins, Bret		Tel: (970) 420-6699																																																								
ECMC contact:				Email: bret.evins@state.co.us																																																										
Type of Well Abandonment Report: <input checked="" type="checkbox"/> Notice of Intent to Abandon <input type="checkbox"/> Subsequent Report of Abandonment																																																														
API Number 05-123-34603-00																																																														
Well Name: Shoemaker				Well Number: AA07-63HN																																																										
Location: QtrQtr: NESE Section: 12 Township: 6N Range: 64W Meridian: 6																																																														
County: WELD Federal, Indian or State Lease Number:																																																														
Field Name: WATTENBERG Field Number: 90750																																																														
Only Complete the Following Background Information for Intent to Abandon																																																														
Latitude: 40.499170 Longitude: -104.490750																																																														
GPS Data: GPS Quality Value: 1.9 Type of GPS Quality Value: PDOP Date of Measurement: 02/23/2012																																																														
Reason for Abandonment: <input type="checkbox"/> Dry <input checked="" type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems																																																														
<input type="checkbox"/> Other																																																														
Casing to be pulled: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Estimated Depth:																																																														
Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, explain details below																																																														
Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, explain details below																																																														
Details:																																																														
Current and Previously Abandoned Zones																																																														
<table><tr><th>Formation</th><th>Perf. Top</th><th>Perf. Btm</th><th>Abandoned Date</th><th>Method of Isolation</th><th>Plug Depth</th></tr><tr><td>NIOBRARA</td><td>7286</td><td>11097</td><td></td><td></td><td></td></tr></table>								Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth	NIOBRARA	7286	11097																																														
Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth																																																									
NIOBRARA	7286	11097																																																												
Total: 1 zone(s)																																																														
Casing History																																																														
<table><tr><th>Casing Type</th><th>Size of Hole</th><th>Size of Casing</th><th>Grade</th><th>Wt/Ft</th><th>Csg/Liner Top</th><th>Setting Depth</th><th>Sacks Cmt</th><th>Cmt Btm</th><th>Cmt Top</th><th>Status</th></tr><tr><td>CONDUCTOR</td><td>19</td><td>16</td><td>J55</td><td>75</td><td>0</td><td>124</td><td></td><td>124</td><td>0</td><td>VISU</td></tr><tr><td>SURF</td><td>13+3/4</td><td>9+5/8</td><td>J55</td><td>36</td><td>0</td><td>832</td><td></td><td>832</td><td>0</td><td>VISU</td></tr><tr><td>1ST</td><td>8+3/4</td><td>7</td><td>P110</td><td>26</td><td>0</td><td>7148</td><td></td><td>7148</td><td>1760</td><td>CBL</td></tr><tr><td>2ND</td><td>6+1/8</td><td>4+1/2</td><td>P110</td><td>11.6</td><td>7005</td><td>11164</td><td></td><td></td><td></td><td></td></tr></table>								Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status	CONDUCTOR	19	16	J55	75	0	124		124	0	VISU	SURF	13+3/4	9+5/8	J55	36	0	832		832	0	VISU	1ST	8+3/4	7	P110	26	0	7148		7148	1760	CBL	2ND	6+1/8	4+1/2	P110	11.6	7005	11164				
Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status																																																				
CONDUCTOR	19	16	J55	75	0	124		124	0	VISU																																																				
SURF	13+3/4	9+5/8	J55	36	0	832		832	0	VISU																																																				
1ST	8+3/4	7	P110	26	0	7148		7148	1760	CBL																																																				
2ND	6+1/8	4+1/2	P110	11.6	7005	11164																																																								

Date Run: 4/25/2024 Doc [#403769650] Well Name: Shoemaker AA07-63HNPage 1 of 3

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6732 with 20 sacks cmt on top. CIBP #2: Depth 2397 with 20 sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 195 sks cmt from 1032 ft. to 0 ft. Plug Type: CASING Plug Tagged: ☒

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 1032 ft. with 160 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Surface Plug Setting Date: _____ Cut and Cap Date: _____ Number of Days from Setting Surface Plug to Capping or Sealing the Well: _____

*Wireline Contractor: _____

*Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

3rd party wildlife surveys will be conducted on this well prior to rigging up for P&A activities.

Notification will be given to any adjacent building unit occupants within a 1000 feet of the wellhead of planned P&A start date.

Please be aware that Form 6 Approval can predate actual rig work by up to several months and that environmental conditions can change quickly over that time. Chevron's Environmental Site Screening Process incorporates full environmental field clearances within 7 days of a scheduled well-work activity once the well is added to the active workover rig schedule. Should sensitive HPH conditions be identified during the screening process, Chevron will delay the work until conditions (nesting) clear and/or consult directly with CPW for guidance and discussion of potential mitigation measures that may be incorporated.

CPW consult not required.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Sharon Strum

Title: Lead Wells Technical Asst

Date: _____

Email: sharon.strum@chevron.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____

Date: _____

CONDITIONS OF APPROVAL, IF ANY LIST

Expiration Date: _____

<u>COA Type</u>	<u>Description</u>
0 COA	

ATTACHMENT LIST

<u>Att Doc Num</u>	<u>Name</u>
403769699	WELLBORE DIAGRAM
403769700	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)