

OIL AND GAS CONSERVATION COMMISSION  
OF THE STATE OF COLORADO

RECEIVED  
MAY - 2 1960  
OIL & GAS  
CONSERVATION COMMISSION

SUNDRY NOTICES AND REPORTS ON WELLS



INSTRUCTIONS

Notice must be given to the Director, and approval obtained in advance of the time when the owner or operator expects to recomplate or abandon a well or to change plans. Within thirty (30) days after recompletion, change of plans, or remedial work, a detailed report of the work done and the results obtained shall be submitted on this form in duplicate for wells on Patented and Federal lands, and in triplicate for wells on State lands. In work that affects only rods, pumps or tubing or other routine work such as, but not limited to, cleaning out to previous total depth, no report is necessary.

|                                     |                                     |                         |                          |
|-------------------------------------|-------------------------------------|-------------------------|--------------------------|
| Notice of Intention to Recomplate   | <input type="checkbox"/>            | Report of Remedial Work | <input type="checkbox"/> |
| Notice of Intention to Change Plans | <input type="checkbox"/>            | Report of Recompletion  | <input type="checkbox"/> |
| Notice of Intention to Abandon Well | <input checked="" type="checkbox"/> | Other                   | <input type="checkbox"/> |

(Check appropriate space)

LEASE NAME Adella Nash WELL NO. 1  
 FIELD New Windsor WILDCAT \_\_\_\_\_ COUNTY Weld  
 LOCATION SW, NE Section 27 Township 7N Range 67W Meridian 6<sup>th</sup> PM  
(Quarter Quarter)  
1918 feet from North Section Line and 1984 feet from East Section Line  
1987 N or S E or W

(DETAILS OF WORK)

This well has been shut in since December 10, 1957. At the time it was shut in it was producing 100% water with 329 barrels of load oil left to be recovered from the sand oil squeeze performed on initial completion.

Since the well has never produced formation oil, it is intended to plug and abandon the well as follows:

1. Place a 50 sx. plug across the Sussex interval 4295 to 4312
2. Place a 15 sx. surface plug and install a suitable marker.

|      |                                     |
|------|-------------------------------------|
| AJW  |                                     |
| DVR  |                                     |
| WRS  |                                     |
| HHM  |                                     |
| JAM  |                                     |
| FJP  |                                     |
| JJD  | <input checked="" type="checkbox"/> |
| FILE |                                     |

I/We hereby swear (or affirm) that the statements herein made are a full and correct report.

APPROVED:

Date May 2 1960  
 Director [Signature]

Company The California Company Date \_\_\_\_\_  
 Address Box 1769, Casper, Wyoming Phone No. 234-6911  
 By [Signature] Title Area Supt.