

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/16/2024

Submitted Date:

04/19/2024

Document Number:

713600954

FIELD INSPECTION FORM

Loc ID 437155 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 66561
Name of Operator: OXY USA INC
Address: PO BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Newville, Toni		toni_newville@oxy.com	
OXY		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437156	WELL	PR	01/01/2024	GW	055-06316	Sheep Mountain Unit 1-12-B	RI

General Comment:

This is a follow up of the previous reclamation inspections #690204290, #713600049. The corrective action of the previous inspections has not been completed. See attached photos and additional details within this report.

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is erosion occurring along the steep portion of the access road. Stormwater is not being diverted off the road to reduce erosion. The sediment traps have filled in with sediment and there are insufficient BMP's installed to prevent erosion of the road.

Corrective Action: install or repair required BMPs per Rule 1002.f.(2)C

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403761494	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6516279
713600955	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6516276