

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403710064

Date Received:

04/27/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10797

Name of Operator: DESERT EAGLE OPERATING LLC

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

MARSHALL WESLEY

wmarshall@prohelium.com

Sanchez, Chris

chris.sanchez@state.co.us

Bulf, Cathy

cathybulf@gmail.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713600640

Inspection Date: 01/18/2024

FIR Submit Date: 01/22/2024

FIR Status: _____

Inspected Operator Information:

Company Name: DESERT EAGLE OPERATING LLC

Company Number: 10797

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

LOCATION - Location ID: 484359

Location Name: Red Rocks

Number: 35-08

County: LAS ANIMAS

Qtrqtr: NWSE

Sec: 35

Twp: 29S

Range: 55W

Meridian: 6

Latitude: 37.471889

Longitude: -103.539533

FACILITY - API Number: 05-071-

-00

Facility ID: 484676

Facility Name: Red Rocks

Number: 35-08

Qtrqtr: NWSE

Sec: 35

Twp: 29S

Range: 55W

Meridian: 6

Latitude: 37.471889

Longitude: -103.539533

CORRECTIVE ACTIONS:

1 CA# 191256

Corrective Action: Install sign to comply with Rule 605.d.

Date: 01/18/2024

Response: CA COMPLETED

Date of Completion: 02/02/2024

Operator Comment: Sign as been installed to comply with Rule 605.d

ECMC Decision: _____

ECMC
Representative:

3 CA# 191258

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)
Clean up stained soils. Implement or modify BMPs for improved material handling and spill prevention.

Date: 01/18/2024

Response: CA COMPLETED

Date of Completion: 02/02/2024

Operator Comment: Rule 1002.f.(2), a rock pad was installed at the intersection of the lease road and the county road to control vehicle tracking, photo attached. The stained soil near the wellhead was removed. Personnel were instructed on vehicle maintenance, material handling, and spill prevention.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The sign has been properly installed, stained soil at the wellhead has been removed, photo attached. A vehicle tracking management rock pad has been installed, photo attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cathy Bulf

Signed: _____

Title: Manager

Date: 4/27/2024 11:55:00 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403710367	Photo - Vehicle Tracking Control
403771630	Photo - Sign and Soil

Total Attach: 2 Files