



00226704

OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES
OF THE STATE OF COLORADO

File in duplicate for Patented and Federal lands.
File in triplicate for State lands.

RECEIVED
FEB 14 1972

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry		5. LEASE DESIGNATION AND SERIAL NO. COLO. OIL & GAS CONSERV. COMMISSION
2. NAME OF OPERATOR R. L. Foree and Max L. Thomas		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 3700 First National Bank Bldg., Dallas, Texas 75202		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 330' FSL, 600' FEL, Sec. 25 At proposed prod. zone		8. FARM OR LEASE NAME Fred Felte
14. PERMIT NO. 71-368		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4950 GR, 4964 KB		10. FIELD AND POOL, OR WILDCAT Wildcat
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 25, T7N, R67W
		12. COUNTY Weld
		13. STATE Colorado

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON

SHOOTING OR ACIDIZING

ABANDONMENT

REPAIR WELL

CHANGE PLANS

(Other) _____

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work Upon approval

- A. Set cement plug across perforation 7924'-7904'
- B. Shoot 4½" N-80 production casing and recover maximum amount.
- C. Set 20 sx. plug at base of surface casing (658')
- D. Cut off surface casing below plow depth.
- E. Set 20 sx. plug in top of surface casing.
- F. Weld steel plate on top of surface casing.

FR	<input checked="" type="checkbox"/>
SP	<input checked="" type="checkbox"/>
HM	<input checked="" type="checkbox"/>
AM	<input checked="" type="checkbox"/>
IS	<input checked="" type="checkbox"/>

18. I hereby certify that the foregoing is true and correct

SIGNED

B. L. Foree

TITLE

Agent

DATE

Feb. 9, 1972

(This space for Federal or State office use)

APPROVED BY

W. L. Rogers

TITLE

DIRECTOR

O & G CONSERV. COMMISSION

DATE

FEB 17 1972

CONDITIONS OF APPROVAL, IF ANY: