



00210018

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES

SUBMIT ORIGINAL AND 1 COPY

FOR OFFICE USE ONLY			
ER	FE	UC	SE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir
Use "APPLICATION FOR PERMIT—" for such proposals.)

<input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> COALBED METHANE <input type="checkbox"/> INJECTION WELL <input checked="" type="checkbox"/> OTHER		5 FEDERAL, INDIAN OR STATE LEASE NO.
2 NAME OF OPERATOR Sunset Producing Co. c/o Arlian, Inc.		6 PERMIT NO. 83-1652
3 ADDRESS OF OPERATOR 1801 Broadway, Suite 1650 CITY STATE ZIP CODE Denver, Colorado 80202		7 API NO. 05-123-11597
4 LOCATION OF WELL (Report location clearly and in accordance with any State requirements See also space 17 below) At surface SE/4NE/4 At proposed prod. zone SAME		8 WELL NAME A.J. Norton
12 COUNTY Weld		9 WELL NUMBER 1
		10 FIELD OR WILDCAT Eaton (19350)
		11 QTR. QTR. SEC., T.R. AND MERIDIAN W SENE 33-T7N-R66W

Check Appropriate Box To Indicate Nature of Notice, Report or Notification

13A. NOTICE OF INTENTION TO:

- ☒ PLUG AND ABANDON
☐ MULTIPLE COMPLETIONS
☐ COMMINGLE ZONES
☐ FRACTURE TREAT
☐ REPAIR WELL
☐ OTHER

13B. SUBSEQUENT REPORT OF:

- ☐ FINAL PLUG AND ABANDONMENT
(SUBMIT 3RD PARTY CEMENT VERIFICATION
AND JOB LOG)
☐ ABANDONED LOCATION (WELL NEVER DRILLED -
SITE MUST BE RESTORED WITHIN 6 MONTHS)
☐ REPAIRED WELL
☐ OTHER

13C. NOTIFICATION OF:

- ☐ SHUT-IN TEMPORARILY ABANDONED
(DATE _____)
(REQUIRED EVERY 6 MONTHS)
☐ PRODUCTION RESUMED
(DATE _____)
☐ LOCATION CHANGE (SUBMIT NEW PLAT)
☐ WELL NAME CHANGE
☐ OTHER

14. DESCRIBE PROPOSED OR COMPLETED OPERATIONS ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent)

15. DATE OF WORK commencing 1-25-92 verbal 1-24-92, Steve Pott

Set bridge plug above at 7,000'.
Set 2 sacks cement on top of bridge plug.
Perforate and cut production casing.
Pull and lay down production casing.
Set 35 sack cement plug at 307' (half-in and half-out of surface pipe).
Set 10 sack cement at top of surface pipe.
Cut off surface pipe off 4' below ground and welded on steel cap.

When weather permits, remove deadmen, back fill pits, cleanup and level location.

16. I hereby certify that the foregoing is true and correct

SIGNED Alvin R. Arlian TELEPHONE NO. 292-4051NAME (PRINT) Alvin R. (Al) Arlian TITLE Agent DATE 1-27-92

(This space for Federal or State office use)

APPROVED Stephen Pott TITLE Sr. Engr. DATE 1/24/92
CONDITIONS OF APPROVAL, IF ANY.