

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403774062

Date Received:
04/30/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:
3 of 3 CAs from the FIR responded to on this Form
3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10611
Name of Operator: LONGS PEAK RESOURCES LLC
Address: 2727 ALLEN PARKWAY SUITE 1850
City: HOUSTON State: TX Zip: 77019
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Brandi Terry</u>	<u>832-748-0912</u>	<u>brandi.terry@boomtownoil.com</u> <u>egeiser@juncap.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 697505241
Inspection Date: 03/28/2024 FIR Submit Date: 04/01/2024 FIR Status:

Inspected Operator Information:

Company Name: LONGS PEAK RESOURCES LLC Company Number: 10611
Address: 2727 ALLEN PARKWAY SUITE 1850
City: HOUSTON State: TX Zip: 77019

LOCATION - Location ID: 439459

Location Name: Motu East Number: 2821-8CH County:
Qtrqtr: SESE Sec: 28 Twp: 12N Range: 65W Meridian: 6
Latitude: 40.972180 Longitude: -104.658350

FACILITY - API Number: 05-123-00 Facility ID: 439459

Facility Name: Motu East Number: 2821-8CH
Qtrqtr: SESE Sec: 28 Twp: 12N Range: 65W Meridian: 6
Latitude: 40.972180 Longitude: -104.658350

CORRECTIVE ACTIONS:

1 CA# 193813

Corrective Action: 1) Operator failed to properly dispose of stained soil around the wellhead per Rule 912.a. Date: 10/11/2023

The corrective date is the date the location was observed out of compliance.

Response: CA COMPLETED Date of Completion: 04/18/2024

Operator Comment: The contaminated soil was disposed of on 4/18/2024 and taken to the Eastern Laramie County Landfill.

ECMC Decision: _____

ECMC Representative:

2 CA# 193814

Corrective Action: Comply with Rule 606

Date: 04/08/2024

Response: CA COMPLETED

Date of Completion: 04/08/2024

Operator Comment:

All trash has been cleaned up off location and load line bucket was replaced.

ECMC Decision: _____

ECMC Representative:

3 CA# 193815

Corrective Action: Best management practices to prevent weed establishment shall be implemented. Control, manage, and prevent weedy, annual vegetation on all topsoil stockpiles. If reseeded is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted.

Date: 04/30/2024

Response: CA COMPLETED

Date of Completion: 04/29/2024

Operator Comment:

Noxious weeds were treated and the site was reseeded per the approved seed mixture.

ECMC Decision: _____

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brandi Terry

Signed: _____

Title: Regulatory Manager

Date: 4/30/2024 12:04:57 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403774137	Seed Mixture
403774139	Weed Treatment
403774167	Photos

Total Attach: 3 Files