

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/15/2024

Submitted Date:

05/01/2024

Document Number:

711900632

## FIELD INSPECTION FORM

Loc ID 317219 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10536

Name of Operator: SMITH ENERGY LLC

Address: 1540 MAIN ST SUITE 218 #334

City: WINDSOR State: CO Zip: 80550

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Chris		smithenergy@live.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
237271	WELL	PR	12/16/1996	GW	121-09772	BURNS 1	PR

**General Comment:**

ROUTINE FIR 2024 SATISFACTORY

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	TWO TRACK GRASSLAND		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	SATISFACTORY		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	SATISFACTORY		
Corrective Action:			Date: _____

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: NONE

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Other	# 0		
Comment:	NO CHANGE		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	237271	Type:	WELL	API Number:	121-09772	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	GW								
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

ECMC Comments		
Comment	User	Date
ROUTINE FIR 2024 SATISFACTORY	schureky	05/01/2024