

STATE OF COLORADO  
**OIL AND GAS CONSERVATION COMMISSION**

DEPARTMENT OF NATURAL RESOURCES  
SUITE 380 LOGAN TOWER BUILDING

1580 LOGAN STREET  
DENVER, COLORADO 80203

(303) 894-2100

WILLIAM R. SMITH  
Director  
DENNIS R. BICKNELL  
Deputy Director



ROY ROMER  
Governor

August 29, 1989

Dave Rebol  
H & R Well Services, Inc.  
# 36980  
0902 Road 4  
Wiggins, CO 80654

Re: New Windsor Field

Dear Mr. Rebol,

This letter is reference to a field inspection on August 22, 1989 in the New Windsor Field. The pit used for the Eaton-Law #2, NWNW 35-7N-67W was overflowing into the field to the east. A copy of the landowners agreement is necessary for this office to allow this to continue or another solution is to enlarge the production water pit, approval of this may be done through Jim Kenney of this office.

The Brownell #1, NENW 35-7N-67W, still has surface equipment that needs to be removed so a final plugging inspection may be made to release this well from your plugging liability.

Yours truly,

A handwritten signature in cursive script that reads "Stephan Pott".

Stephan Pott  
Petroleum Engineer