

**EVERGREEN NATURAL RESOURCES
SPILL / RELEASE RESPONSE FORM**

Spill/Release Point
Name & Number Lorencito 13-17

Cause of Spill: Puckering leak

Discovered By: Ryan Costa (ELMC)

Investigated By: T. Fernandez

Isolated By: M. Serna

Was Spill Contained
Within Berm? YES / NO Weather Conditions: 62° Sunny, Calm

Description of Photos/Other Notes (Number photos and place number on drawing.)	
1. Well Placed	
2. Spill source	
3. Spill path facing S	
4. Spill path facing SE in diversion	
5. Spill path facing SE off loc.	
6. Spill path below pad facing N	
7. Spill path in bare ditch facing W	
8. End of spill facing W	

Related Coordinates		
Lat / Long		
Start:	37.0795519	-104.809537
Drilling 1	37.079798	-104.809620
Drilling 2	37.079714	-104.809580
Drilling 3	37.079627	-104.809657
End	37.079351	-104.809489

Were any of the following impacted?	
Waters of the State	Yes / <u>NO</u>
Residence/Occupied Structure	Yes / <u>NO</u>
Surface Water Supply Area	Yes / <u>NO</u>
Public Byway	Yes / <u>NO</u>
Livestock	Yes / <u>NO</u>

Date & Time of Incident: 4-28-24 1330

Facility Type: Well Tank / Gathering / Pit / Other: _____

	Water	Oil	Other:
Estimated BBLs:	<u>4.5</u>	<u>0</u>	<u>0</u>
BBLs Recovered:	<u>0</u>	<u>0</u>	<u>0</u>

Depth of Impact: 2"

Approximate Length & Width of Spill: L 255 ft W 3 ft

