

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
402679071

Date Received:  
05/10/2021

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 76175  
Name of Operator: SANDLIN OIL CORP  
Address: 1580 LINCOLN ST SUITE 580  
City: DENVER State: CO Zip: 80203

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Pesicka, Conor</u>		<u>conor.pesicka@state.co.us</u>
<u>Sandlin, Gary</u>		<u>SandlinOilCorporation@gmail.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 701002668  
Inspection Date: 03/30/2021 FIR Submit Date: 03/31/2021 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SANDLIN OIL CORP Company Number: 76175  
Address: 1580 LINCOLN ST SUITE 580  
City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 320989

Location Name: RD JONES-633S42W Number: 13CNW County: BACA  
Qtrqtr: CNW Sec: 13 Twp: 33S Range: 42W Meridian: 6  
Latitude: 37.174563 Longitude: -102.108727

FACILITY - API Number: 05-009-00 Facility ID: 205691

Facility Name: RD JONES Number: 1  
Qtrqtr: CNW Sec: 13 Twp: 33S Range: 42W Meridian: 6  
Latitude: 37.174563 Longitude: -102.108727

CORRECTIVE ACTIONS:

1  CA# 147888

Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1). Date: 04/30/2021

Response: CA COMPLETED Date of Completion: 05/10/2021

Operator Comment: Disconnected tank from water line. Well is SI.

ECMC Decision: Approved pending re-inspection

ECMC Representative:

2  CA# 147889

Corrective Action: Install lease sign

Date: 04/30/2021

Response: CA COMPLETED

Date of Completion: 05/10/2021

Operator Comment: Installed lease sign so cattle can't get to it.

ECMC Decision: Approved pending re-inspection

ECMC Representative:

3  CA# 147890

Corrective Action: Install sign to comply with Rule 605.h.

Date: 04/30/2021

Response: CA COMPLETED

Date of Completion: 05/10/2021

Operator Comment: Installed NFPA lable as requested.

ECMC Decision: Approved pending re-inspection

ECMC Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: All corrective requests have been completed as requested.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kathie D. Sandlin

Signed: \_\_\_\_\_

Title: President

Date: 5/10/2021 12:43:27 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
402679071	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files