

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403714134

Date Received:

03/10/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714300041

Inspection Date: 03/01/2024

FIR Submit Date: 03/04/2024

FIR Status: _____

Inspected Operator Information:

Company Name: CRESTONE PEAK RESOURCES OPERATING LLC

Company Number: 10633

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 322691

Location Name: ANDERSON TRUST C
62N68W

Number: 32NENE

County: _____

Qtrqr: NENE Sec: 32 Twp: 2N Range: 68W Meridian: 6

Latitude: 40.099832 Longitude: -105.022216

FACILITY - API Number: 05-123- -00

Facility ID: 481942

Facility Name: Anderson Trust C1 Spill

Number: _____

Qtrqr: NENE Sec: 32 Twp: 2N Range: 68W Meridian: 6

Latitude: 40.099832 Longitude: -105.022216

CORRECTIVE ACTIONS:

1 CA# 192615

Corrective Action: Secure access to excavation in compliance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v.

Date: 03/11/2024

Response: CA COMPLETED

Date of Completion: 03/08/2024

Operator
Comment:

Operator has appropriately repaired the fencing around the excavation to comply with Rule 913.b.(5).B.i.

ECMC Decision: _____

Comment:	CA follow-up has been completed for this location.
----------	--

Print Name: Ashley Noonan Signed: _____
Title: Sr Regulatory Analyst Date: 3/10/2024 3:51:27 PM

<u>Document Number</u>	<u>Description</u>
403714134	FIR RESOLUTION SUBMITTED
403714138	Inspection Resolution Report

Page 2 of 2