

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403499966

Date Received:  
08/17/2023

**FIR RESOLUTION FORM**

Overall Status: FRQ

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed  
1 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Romana Cowden</u>	<u>720-951-5895</u>	<u>COGCC.inspections@caerusoilandgas.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 708901365  
Inspection Date: 08/15/2023 FIR Submit Date: 08/15/2023 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC Company Number: 10456  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335385

Location Name: BENZEL-66S93W Number: 25SESW County: \_\_\_\_\_  
Qtrqtr: SWNE Sec: 25 Twp: 6S Range: 93W Meridian: 6  
Latitude: 39.492260 Longitude: -107.726460

FACILITY - API Number: 05-045-00 Facility ID: 335385

Facility Name: BENZEL-66S93W Number: 25SESW  
Qtrqtr: SWNE Sec: 25 Twp: 6S Range: 93W Meridian: 6  
Latitude: 39.492260 Longitude: -107.726460

CORRECTIVE ACTIONS:

1  CA# 178575

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved. Date: 08/30/2023

Response: FACTUAL REVIEW REQUEST

Basis for Review: Action requested was already completed prior to the inspection

Operator Comment: Photos show very minimal sediment in the BMP. This level of sediment is within our maintenance threshold, as we typically maintain sediment traps and detention ponds when they contain more sediment. Performing maintenance too often damages established vegetation. We are happy to meet on site to discuss.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: \_\_\_\_\_

Title: EHS

Date: 8/17/2023 9:20:11 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

403499966	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files