

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401773727

Date Received:

11/14/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

8 of 9 CAs from the FIR responded to on this Form

8 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 36200

Name of Operator: GRYNBERG* JACK DBA GRYNBERG PETROLEUM CO

Address: 3600 S. YOSEMITE ST - STE 900

City: DENVER State: CO Zip: 80237-1830

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Miller, R.

r.miller@grynberg.com

Edelen, Randy

r.edelen@grynberg.com

Grynberg Petroleum

grynpetro@grynberg.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 685200541

Inspection Date: 08/15/2018

FIR Submit Date: 08/21/2018

FIR Status: _____

Inspected Operator Information:

Company Name: GRYNBERG* JACK DBA GRYNBERG PETROLEUM CO

Company Number: 36200

Address: 3600 S. YOSEMITE ST - STE 900

City: DENVER State: CO Zip: 80237-1830

LOCATION - Location ID: 313507

Location Name: AKIN, MARY UNIT-N38N14W Number: 27SESW County: MONTEZUMA

Qtrqtr: SESW Sec: 27 Twp: 38N Range: 14W Meridian: N

Latitude: 37.518394 Longitude: -108.383922

FACILITY - API Number: 05-083-00 Facility ID: 224313

Facility Name: AKIN, MARY UNIT Number: 2

Qtrqtr: SESW Sec: 27 Twp: 38N Range: 14W Meridian: N

Latitude: 37.518394 Longitude: -108.383922

CORRECTIVE ACTIONS:

1 CA# 118026

Corrective Action: remove all trash from location and along access road.

Date: 09/21/2018

Response: CA COMPLETED

Date of Completion: 09/11/2018

Operator Comment: All trash removed and properly disposed

ECMC Decision: _____

ECMC
Representative:

2 CA# 118027

Corrective Action: Maintain sign per Rule 210

Date: 08/24/2018

Response: CA COMPLETED

Date of Completion: 09/11/2018

Operator
Comment: Sign was reset.

ECMC Decision: _____

ECMC
Representative:

3 CA# 118028

Corrective Action: Install at least 1 wind indicator

Date: 08/24/2018

Response: CA COMPLETED

Date of Completion: 09/11/2018

Operator
Comment: Wind indicator was installed.

ECMC Decision: _____

ECMC
Representative:

5 CA# 118030

Corrective Action: Remove all equipment, tanks, parts and supplies not in use per Rules 603.f and 1002

Date: 09/21/2018

Response: CA COMPLETED

Date of Completion: 09/11/2018

Operator
Comment: There is no equipment that is not in use. Work is proceeding on pipeline.

ECMC Decision: _____

ECMC
Representative:

6 CA# 118031

Corrective Action: mark all 4 deadmen/rig anchors per Rule 1002

Date: 09/21/2018

Response: CA COMPLETED

Date of Completion: 09/11/2018

Operator
Comment: All deadmen were marked.

ECMC Decision: _____

ECMC
Representative:

7 CA# 118032

Corrective Action: Install H2S warning sign on access road or at gate so it is at least 200' from entrance to location and no more than 500'.

Date: 08/24/2018

Response: CA COMPLETED

Date of Completion: 09/11/2018

Operator Comment: Location has correct signage.

ECMC Decision:

ECMC Representative:

8 CA# 118033

Corrective Action: Install valid 24-hour operator contact number and number to call in emergency (911)

Date: 08/24/2018

Response: CA COMPLETED

Date of Completion: 09/11/2018

Operator Comment: Contact information was changed on tanks and signs.

ECMC Decision:

ECMC Representative:

9 CA# 118034

Corrective Action: Produce (after performing a succesful MIT) or plug well.

Date: 11/23/2018

Response: CA COMPLETED

Date of Completion: 09/11/2018

Operator Comment: Work currently ongoing to produce this well.

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: MIT and corrective actions were performed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Randy Edelen

Signed:

Title: RegulatoryEngineeringMgr

Date: 11/14/2018 3:49:52 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401773727	FIR RESOLUTION SUBMITTED
401773748	H2S Sign at Location
401773769	Deadman Marker
401773771	Deadman Marker
401773772	H2S Sign at Access Road

401773773	Tanks Labels
401773774	Wellhead Sign and Windsock

Total Attach: 7 Files