

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403229194

Date Received:
11/15/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

| Contact Name | Phone | Email |
|------------------|-------|---------------------------------------|
| . General | | FarmingtonRegulatoryTechs@hilcorp.com |
| Labowskie, Steve | | steve.labowskie@state.co.us |

ECMC INSPECTION SUMMARY:

FIR Document Number: 702500759
Inspection Date: 11/09/2022 FIR Submit Date: 11/09/2022 FIR Status:

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326297

Location Name: HUBER-LEWIS-N35N8W Number: 33SWSE County: LA PLATA
Qtrqr: SWSE Sec: 33 Twp: 35N Range: 8W Meridian: N
Latitude: 37.253760 Longitude: -107.747900

FACILITY - API Number: 05-067-00 Facility ID: 216188

Facility Name: HUBER-LEWIS Number: 2-33
Qtrqr: SWSE Sec: 33 Twp: 35N Range: 8W Meridian: N
Latitude: 37.253760 Longitude: -107.747900

CORRECTIVE ACTIONS:

1 CA# 166021

Corrective Action: Remove impacted material and dispose of in approved manner per rule 906 and 1002.f. Date: 11/17/2022

Response: CA COMPLETED Date of Completion: 11/14/2022

Operator Comment: All impacted material at compressor skid and pump jack has been removed and treated with Simple Green. See attached photos.

ECMC Decision:

ECMC
Representative:

2 CA# 166022

Corrective Action: Install sign to comply with Rule 605.h.

Date: 09/06/2022

Response: CA COMPLETED

Date of Completion: 11/14/2022

Operator
Comment: Tank capacity is legible. See attached photo.

ECMC Decision: _____

ECMC
Representative:

3 CA# 166023

Corrective Action: Remove oil and oily residue and dispose of in approved manner per rule 906 and 1002.f.

Date: 11/11/2022

Response: CA COMPLETED

Date of Completion: 11/14/2022

Operator
Comment: All impacted material at compressor skid and pump jack has been removed and treated with Simple Green. See attached photos.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 11/15/2022 5:46:20 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|----------------------------------|
| 403229194 | FIR RESOLUTION SUBMITTED |
| 403229195 | Huber Lewis 2-33 Resolved Photos |

Total Attach: 2 Files