

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403773803

Date Received:
04/30/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Romana Cowden	720-951-5895	COGCC.inspections@caerusoilandgas.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 696205521
Inspection Date: 01/05/2024 FIR Submit Date: 01/10/2024 FIR Status:

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC Company Number: 10456
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334643

Location Name: SOURS-67S93W Number: 15NWSW County:
Qtrqtr: NWN Sec: 15 Twp: 7S Range: 93W Meridian: 6
W
Latitude: 39.443360 Longitude: -107.767970

FACILITY - API Number: 05-045-00 Facility ID: 334643

Facility Name: SOURS-67S93W Number: 15NWSW
Qtrqtr: NWN Sec: 15 Twp: 7S Range: 93W Meridian: 6
W
Latitude: 39.443360 Longitude: -107.767970

CORRECTIVE ACTIONS:

1 CA# 189973

Corrective Action: Install or repair containment BMP; ensure containment remains impervious to contain a spill or release. Date: 01/05/2024

Response: CA COMPLETED Date of Completion: 04/29/2024

Operator Comment: Liner was repaired, see photo.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 4/30/2024 10:29:10 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403773803	FIR RESOLUTION SUBMITTED
403773810	Liner was repaired

Total Attach: 2 Files