

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403696936

Date Received:

02/23/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 7800

Name of Operator: BEREN CORPORATION

Address: 2020 N BRAMBLEWOOD STREET

City: WICHITA State: KS Zip: 67206

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Kay, Michael

316-249-7597

kaym@berexco.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 711900205

Inspection Date: 01/26/2024

FIR Submit Date: 01/26/2024

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: BEREN CORPORATION

Company Number: 7800

Address: 2020 N BRAMBLEWOOD STREET

City: WICHITA State: KS Zip: 67206

#### LOCATION - Location ID: 312144

Location Name: BREWER 'A'-68N53W Number: 15SESE County: LOGAN

Qtrqtr: SESE Sec: 15 Twp: 8N Range: 53W Meridian: 6

Latitude: 40.655980 Longitude: -103.280983

#### FACILITY - API Number: 05-075- -00 Facility ID: 218987

Facility Name: BREWER 'A' Number: 3

Qtrqtr: SESE Sec: 15 Twp: 8N Range: 53W Meridian: 6

Latitude: 40.655980 Longitude: -103.280983

### CORRECTIVE ACTIONS:

1 CA# 191386

Corrective Action: REPAIR LEAK AT GEARBOX PER RULE 608e

Date: 02/10/2024

Response: CA COMPLETED

Date of Completion: 02/15/2024

Operator Comment: Leak at Gearbox has been repaired, photos of pumping unit after repair work are attached as Figure 1 and Figure 2.

ECMC Decision: \_\_\_\_\_

Lease road repaired and graded. Photos of lease road are attached as Figure 3 and Figure 4.

\_\_\_\_\_

Gearbox leak has been repaired. Roustabouts cleaned up location. Photos of wellsite after cleanup was completed are attached as Figure 5 and Figure 6.

Comment:	Cleanup was done as soon as possible given the schedules of roustabouts used to do the cleanup work.
----------	--

Signed:

Date: 2/23/2024 12:59:29 PM

<u>Document Number</u>	<u>Description</u>
403696936	FIR RESOLUTION SUBMITTED
403696959	Evidence leak on gearbox was repaired.
403696960	Evidence leak on gearbox was repaired.
403696973	Photo of repaired lease road at wellsite looking South.
403696975	Photo of repaired lease road looking North.
403696978	Photo of cleaned up well location.
403696980	Photo of cleaned up well location.

Page 2 of 2