

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403714987

Date Received:
03/11/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Victoria Dizghinjili	303-825-4822	vdizghinjili@kpk.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713300655
Inspection Date: 03/05/2024 FIR Submit Date: 03/05/2024 FIR Status:

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 320276

Location Name: JOHN WEIGANDT B-61S67W Number: 3NWNE County: ADAMS
Qtrqtr: NWNE Sec: 3 Twp: 1S Range: 67W Meridian: 6
Latitude: 39.998920 Longitude: -104.873040

FACILITY - API Number: 05-001-00 Facility ID: 203332

Facility Name: JOHN WEIGANDT B Number: 1
Qtrqtr: NWNE Sec: 3 Twp: 1S Range: 67W Meridian: 6
Latitude: 39.998920 Longitude: -104.873040

CORRECTIVE ACTIONS:

1 CA# 192855

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210. Date: 04/08/2024

Response: CA COMPLETED Date of Completion: 03/11/2024

Operator Comment: This well does not fit the definition of Temporarily Abandoned as defined in ECMC 100 Series rules. Instead, this well is Shut-in due to the ECMC Director's 901.a Order dated April 12, 2021. It is capable of production without a downhole intervention, removal of a plug, or addition of equipment. KPK disagrees with the requirement to conduct an MIT on this well and has previously requested a partial withdrawal of the 901.a Order and the ability to unload well liquids thereby resetting the clock for MIT testing. In the alternative, KPK proposed continuously monitor bradenhead pressures to satisfy the MIT requirement; this practice was previously approved and

implemented by another operator. KPK renews it request to unload the Shut-in 901.a Order wells.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed: _____

Title: Engineering Tech

Date: 3/11/2024 1:54:07 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403714987	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files