

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403442817

Date Received:
06/22/2023

FIR RESOLUTION FORM

Overall Status: BOTH

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

2 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Kosola, Jason</u>		<u>jason.kosola@state.co.us</u>
<u>Tammy Jones</u>		<u>FarmingtonRegulatoryTechs@hilcorp.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 712700308
Inspection Date: 06/20/2023 FIR Submit Date: 06/21/2023 FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 307014

Location Name: ALLISON UNIT-N32N6W Number: 19SENE County: LA PLATA
Qtrqtr: SENE Sec: 19 Twp: 32N Range: 6W Meridian: N
Latitude: 37.003070 Longitude: -107.533570

FACILITY - API Number: 05-067-00 Facility ID: 295743

Facility Name: ALLISON UNIT Number: 116T (LOWER HOL)
Qtrqtr: SENE Sec: 19 Twp: 32N Range: 6W Meridian: N
Latitude: 37.003070 Longitude: -107.533570

CORRECTIVE ACTIONS:

1 CA# 173443

Corrective Action: Recover free liquids and properly dispose in accordance with 905.c. Rule 1002.f. Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 06/22/2023

Response: CA COMPLETED Date of Completion: 06/22/2023

Operator Comment: installed new packing in the pumping unit stuffing box. I removed the stained dirt around the wellhead, and cleaned the wellhead up.

ECMC Decision: Approved pending re-inspection

ECMC Representative:

2 CA# 173444

Corrective Action: Perform annual bradenhead test and submit Form 17 per Rule 419.c.

Date: 07/21/2023

Response: FACTUAL REVIEW REQUEST

Basis for Review: CA dates are not per the guidelines

Operator Comment: BH Tests are done Annually before Year End.

ECMC Decision: **Not Approved**

ECMC Representative: Dates changed on FIR.

3 CA# 173445

Corrective Action: Rule 1002.f. Site stabilization.

Date: 07/05/2023

Response: CA COMPLETED

Date of Completion: 06/22/2023

Operator Comment: location stabilized and filled in the ruts.

ECMC Decision: Approved pending re-inspection

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: See attached Resolved photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tammy Jones

Signed: _____

Title: Ops/RegulatoryTech

Date: 6/22/2023 2:40:20 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403442817	FIR RESOLUTION SUBMITTED
403442835	Resolved Photos

Total Attach: 2 Files