

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403742268

Date Received:

04/04/2024

## FIR RESOLUTION FORM

**Overall Status:**

**CA Summary:**

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: <u>10705</u>	Contact Name and Telephone:
Name of Operator: <u>EVERGREEN NATURAL RESOURCES LLC</u>	Name: _____
Address: <u>1875 LAWRENCE ST STE 1150</u>	Phone: (    )                      Fax: (    )
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>	Email: _____

**Additional Operator Contact:**

Contact Name	Phone	Email
<u>Distribution, Evergreen</u>	<u>719-846-7898</u>	<u>cogcc.evergreen@enrllc.com</u>
<u>Adamczyk, Megan</u>		<u>megan.adamczyk@state.co.us</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 695109087  
Inspection Date: 02/06/2024                      FIR Submit Date: 03/21/2024                      FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: EVERGREEN NATURAL RESOURCES LLC                      Company Number: 10705  
Address: 1875 LAWRENCE ST STE 1150  
City: DENVER                      State: CO                      Zip: 80202

**LOCATION** - Location ID: 334321

Location Name: HILL-632S66W                      Number: 22NWSE                      County: LAS ANIMAS  
Qtrqtr: NWSE                      Sec: 22                      Twp: 32S                      Range: 66W                      Meridian: 6  
Latitude: 37.240640                      Longitude: -104.764580

**FACILITY** - API Number: 05-071- -00                      Facility ID: 260968

Facility Name: HILL                      Number: 33-22  
Qtrqtr: NWSE                      Sec: 22                      Twp: 32S                      Range: 66W                      Meridian: 6  
Latitude: 37.240640                      Longitude: -104.764580

**CORRECTIVE ACTIONS:**

**1** CA# 193549

Corrective Action: inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. REMOVE PUMPJACK, CONCRETE PAD, COMPACT AND STABILIZE CONCRETE PAD TO ILIMINATE THE BANGING NOISE ON THE DOWN STROKE OF THE PUMPJACK.                      Date: 02/17/2024

Response: CA COMPLETED                      Date of Completion: 04/03/2024

Operator Comment: Pumpjack pad stabilized per rule 608.e

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tracy Dyke

Signed: \_\_\_\_\_

Title: Construction Technician

Date: 4/4/2024 7:46:17 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

403742268	FIR RESOLUTION SUBMITTED
403742269	Hill pad reset

Total Attach: 2 Files