

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402182171

Date Received:

01/10/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Inspections, All

inspections@catamountep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 685200612

Inspection Date: 06/18/2019

FIR Submit Date: 06/28/2019

FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 320891

Location Name: TABOR-N33N5W Number: 3NENE County: ARCHULETA

Qtrqtr: Lot 1 Sec: 3 Twp: 33N Range: 5W Meridian: N

Latitude: 37.139750 Longitude: -107.370780

FACILITY - API Number: 05-007- -00 Facility ID: 282169

Facility Name: TABOR Number: 1

Qtrqtr: Lot 1 Sec: 3 Twp: 33N Range: 5W Meridian: N

Latitude: 37.139750 Longitude: -107.370780

CORRECTIVE ACTIONS:

1 CA# 126547

Corrective Action: Remove equipment. Do not stored or stage equipment, parts, supplies, trash without approved Form 4 from COGCC.

Date: _____

Response: CA COMPLETED

Date of Completion: 06/28/2019

Operator Comment: Removed all equipment.

ECMC Decision: _____

ECMC
Representative:

2 CA# 126548

Corrective Action: adequately makr all anchors

Date: 07/30/2019

Response: CA COMPLETED

Date of Completion: 07/30/2019

Operator
Comment: Anchors were removed.

ECMC Decision:

ECMC
Representative:

3 CA# 126549

Corrective Action: Stormwater controls (run-on and runoff) need to be installed to stabilize erosion within the project area by December 21, 2018. Erosion controls such as mulch, hydromulch, or erosion blankets are needed on the well pad cut-slope until vegetation becomes established. This should be installed in coordination with seeding efforts described above

Date: 01/15/2019

Response: CA COMPLETED

Date of Completion: 11/18/2019

Operator
Comment: Cut Slopes have been reclaimed and seeded.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed:

Title: Geo/Eng Tech

Date: 1/10/2020 3:13:00 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402182171	FIR RESOLUTION SUBMITTED
402282715	Remedial Report

Total Attach: 2 Files