

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2024

Submitted Date:

05/09/2024

Document Number:

707800930

FIELD INSPECTION FORMLoc ID 436801 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10805

Name of Operator: FULCRUM ENERGY OPERATING LLC

Address: 240 SAINT PAUL STREET SUITE 502

City: DENVER State: CO Zip: 80206

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Fulcrum		inspections@fulcrumeo.com	
Penner, annalee		annalee@fulcrumef.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436790	WELL	SI	10/01/2023	OW	057-06526	Surprise Unit 2-08H	SI

General Comment:**ECMC Inspection Report Summary**

On Wednesday 5/1/2024, I, Inspector Scott Ramsey, conducted a routine inspection at Surprise unit 2-18H pad, at Location # 436801 in Jackson county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Well signage lacking information (API)
2. Random debris
3. Silt fencing not trenched in/installed properly

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Well signage lacking information (API)		
Corrective Action:	Provide proper signage	Date:	06/26/2024
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Fulcrum 911/970-594-0477

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	05/24/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank in plastic containment		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Well head		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	436790	Type:	WELL	API Number:	057-06526	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="Last produced 10/2023"/>									
Corrective Action: <input type="text"/> Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Silt Fences	Fail					
Berms						

Comment: 1. Silt fencing not trenched in/installed properly
Maintenance relative to storm water runoff, operators shall consider seasonal factors, such as winter snow cover and spring runoff from snowmelt, to ensure site conditions and controls are adequate and in place to effectively manage storm water.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800937	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6542642