

FORM
6Rev
11/20

State of Colorado

Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

403785348

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

ECMC Operator Number: 10633

Contact Name: Derek Clark

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Phone: (720) 270-4921

Address: 555 17TH STREET SUITE 3700

Fax:

City: DENVER

State: CO

Zip: 80202

Email: declark@civiresources.com

For "Intent" 24 hour notice required,

Name: Carlile, Craig

Tel: (970) 629-8279

ECMC contact:

Email: craig.carlile@state.co.us

Type of Well Abandonment Report: ☒ Notice of Intent to Abandon ☐ Subsequent Report of Abandonment

API Number 05-123-20398-00

Well Name: KIYOTA

Well Number: 44-35

Location: QtrQtr: SESE

Section: 35

Township: 3N

Range: 67W

Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WATTENBERG

Field Number: 90750

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.175984

Longitude: -104.851394

GPS Data: GPS Quality Value: 1.8 Type of GPS Quality Value: PDOP Date of Measurement: 05/13/2009

Reason for Abandonment: ☐ Dry ☐ Production Sub-economic ☐ Mechanical Problems☒ Other P&A due to OOSPLCasing to be pulled: ☒ Yes ☐ No

Estimated Depth: 3000

Fish in Hole: ☐ Yes ☒ No

If yes, explain details below

Wellbore has Uncemented Casing leaks: ☐ Yes ☒ No

If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7331	7341			
J SAND	7764	7834			
NIOBRARA	7104	7124			

Total: 3 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J-55	24	0	746	555	746	0	CALC
1ST	7+7/8	4+1/2	J-55	11.6	0	7925	250	7925	6600	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7700 with 2 sacks cmt on top. CIBP #2: Depth 7000 with 2 sacks cmt on top.

CIBP #3: Depth with sacks cmt on top. CIBP #4: Depth with sacks cmt on top.

CIBP #5: Depth with sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 83 sks cmt from 3100 ft. to 2800 ft.

Plug Type: STUB PLUG

Plug Tagged: ☐

Set sks cmt from ft. to ft.

Plug Type:

Plug Tagged: ☐

Set sks cmt from ft. to ft.

Plug Type:

Plug Tagged: ☐

Set sks cmt from ft. to ft.

Plug Type:

Plug Tagged: ☐

Set sks cmt from ft. to ft.

Plug Type:

Plug Tagged: ☐

Perforate and squeeze at ft. with sacks. Leave at least 100 ft. in casing CICR Depth

Perforate and squeeze at ft. with sacks. Leave at least 100 ft. in casing CICR Depth

Perforate and squeeze at ft. with sacks. Leave at least 100 ft. in casing CICR Depth

(Cast Iron Cement Retainer Depth)

Set 265 sacks half in. half out surface casing from 846 ft. to 0 ft.

Plug Tagged: ☐

Set sacks at surface

Cut four feet below ground level, weld on plate

Above Ground Dry-Hole Marker: ☐ Yes

☐ No

Set sacks in rat hole

Set sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: ft. of inch casing

Number of Days from Setting Surface Plug to Capping or Sealing the Well:

Surface Plug Setting Date: Cut and Cap Date:

*Wireline Contractor:

*Cementing Contractor:

Type of Cement and Additives Used:

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

Proposed WBD Attached
CPW consult is not required for big game HPH.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed:

Print Name: Ashley Noonan

Title: Sr. Regulatory Analyst

Date:

Email: regulatory@civiresources.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved:

Date:

CONDITIONS OF APPROVAL, IF ANY LIST

Expiration Date:

<u>COA Type</u>	<u>Description</u>
0 COA	

ATTACHMENT LIST

<u>Att Doc Num</u>	<u>Name</u>
403786011	WELLBORE DIAGRAM

Total Attach: 1 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)