

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403788250

Date Received:
05/13/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 697505254

Inspection Date: 04/04/2024

FIR Submit Date: 04/09/2024

FIR Status: _____

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION

Company Number: 10071

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 420726

Location Name: Lion Creek Number: 08-25H County: _____

Qtrqtr: SESE Sec: 25 Twp: 11N Range: 64W Meridian: 6

Latitude: 40.887067 Longitude: -104.487806

FACILITY - API Number: 05-123-00 Facility ID: 420726

Facility Name: Lion Creek Number: 08-25H

Qtrqtr: SESE Sec: 25 Twp: 11N Range: 64W Meridian: 6

Latitude: 40.887067 Longitude: -104.487806

CORRECTIVE ACTIONS:

1 CA# 194128

Corrective Action: Comply with Rule 1004 to perform additional reclamation activities for the access road.

Date: 05/13/2024

Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Response: CA COMPLETED

Date of Completion: 05/09/2024

Operator has reported that the location has been appropriately mowed to address weeds and undesirable

Operator Comment: vegetation. It has also been noted that the access road has been re-seeded and straw crimped to provide stabilization and promote more uniform future growth. Bare areas have also been addressed along the old access road. Location currently complies with Rule 1004.

ECMC Decision: _____

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: _____

Title: Sr Regulatory Analyst

Date: 5/13/2024 12:16:57 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403788319	Inspection Resolution Report
-----------	------------------------------

Total Attach: 1 Files