

**Operator:** HIGHPOINT OPERATING CORPORATION

**Location Name:** Lion Creek 08-25H

**Loc ID:** 420726

**Inspection:** 697505254



**Exhibit A**



**Exhibit B**



**Exhibit C**



**Exhibit D**



**Exhibit E**



**Exhibit F**

**CA:** Operator has performed final reclamation activities for the location and the access road. The location meets Rule 1004 vegetation standards. However, the access road has bare patches without uniform vegetative establishment after approximately four years since final reclamation was performed. Comply with Rule 1004 to perform additional reclamation activities for the access road. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

**CA Resolution:** Operator has reported that the location has been appropriately mowed to address weeds and undesirable vegetation. It has also been noted that the access road has been re-seeded and straw crimped to provide stabilization and promote more uniform future growth. Bare areas have also been addressed along the old access road. Location currently complies with Rule 1004.