

OIL AND GAS CONSERVATION COMMISSION  
DEPARTMENT OF NATURAL RESOURCES  
OF THE STATE OF COLORADO

File in duplicate for Patented and Federal lands.  
File in triplicate for State lands.

RECEIVED  
SEP 16 1985

COLO. OIL & GAS CONSERV. COMM.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Plugged and Abandoned		5. LEASE DESIGNATION (AND SERIAL NO.)
2. NAME OF OPERATOR ENERGY MINERALS CORPORATION		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 1000 Security Life Building Denver, Colorado 80202		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface SW SE (1905' FEL & 721' FSL) At proposed prod. zone Same		8. FARM OR LEASE NAME DAVID (59515)
14. PERMIT NO. 81-44		9. WELL NO. #1
15. ELEVATIONS (Show whether DP, RT, GR, etc.) 4945' GR 4955' KB		10. FIELD AND POOL, OR WILDCAT Spindle
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 36-T1N-R67W
		12. COUNTY Weld
		13. STATE Colorado

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
(Other)

PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
ABANDON ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐  
FRACTURE TREATMENT ☐  
SHOOTING OR ACIDIZING ☐  
(Other)

REPAIRING WELL ☐  
ALTERING CASING ☐  
ABANDONMENT ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work 8-19-85 to 8-29-85

1. Pump 20 sx. cement plug @ 4842' (perforations).
2. Shot off casing @ 3600'.
3. Pump 20 sx cement plug @ 1250'.
4. Pump 20 sx. cement plug @ 700'.
5. Pump 25 sx. cement plug @ 227' (1/2 in & 1/2 out of surface csg.).
6. Cut off surface csg. below plow depth.
7. Dump 10 sx. cement plug @ surface.
8. Weld on plate.

EXHAUSTED  
OIL WELL

18. I hereby certify that the foregoing is true and correct

SIGNED Cordelle Fehr  
Cordelle Fehr

TITLE Production Secretary

DATE 09-12-85

(This space for Federal or State office use)

APPROVED BY Wm. R. Smith  
CONDITIONS OF APPROVAL, IF ANY:

DIRECTOR  
O & G Cons. Comm.

DATE SEP 23 1985



00036411

WRS  
FJP  
H  
JAM  
RCC  
LAR  
CGM  
ED