

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403790227

Date Received:

05/14/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10766
Name of Operator: ARKOMA OPERATIONS LLC
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Price, Andrew

(918) 260-8324

aprice@arkomaops.com

.General

SJBcompliance@arkomaops.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000630

Inspection Date: 04/03/2024

FIR Submit Date: 04/08/2024

FIR Status: _____

Inspected Operator Information:

Company Name: ARKOMA OPERATIONS LLC

Company Number: 10766

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA

State: OK

Zip: 74114

LOCATION - Location ID: 311923

Location Name: MCELVAIN-HARMON-N33N8W

Number: 19NWNE

County: LA PLATA

Qtrqr: NWNE

Sec: 19

Twp: 33N

Range: 8W

Meridian: N

Latitude: 37.093840

Longitude: -107.755580

FACILITY - API Number: 05-067-

-00

Facility ID: 89089

Facility Name: MCELVAIN-HARMON

Number: 1A

Qtrqr: NWNE

Sec: 19

Twp: 33N

Range: 8W

Meridian: N

Latitude: 37.093840

Longitude: -107.755580

CORRECTIVE ACTIONS:

1 ☒ CA# 194106

Corrective Action: Comply with rule 606, remove and properly dispose of debris.

Date: 04/15/2024

Response: CA COMPLETED

Date of Completion: 05/14/2024

Operator
Comment: Woody plank debris removed.

ECMC Decision: Approved via an AMI

Date Run: 5/20/2024 Doc [#403790227]

ECMC
Representative:

Per photo included in attachment provided by operator the woody debris has been removed.

2 ☒ CA# 194107

Corrective Action: Comply with rule 1002 Install or repair required BMPs.

Date: _____

Response: CA COMPLETED

Date of Completion: 05/14/2024

Operator
Comment:

Erosion on locations were properly addressed by adding material to stabilize the location.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment: See attached remedial report.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: _____

Title: Engineering Analyst

Date: 5/14/2024 2:06:56 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403790227	FIR RESOLUTION SUBMITTED
403790239	McElvain-Harmon 1A Remedial Report (714000630)

Total Attach: 2 Files