

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/22/2024

Submitted Date:

05/22/2024

Document Number:

711900810

FIELD INSPECTION FORM

Loc ID: 312315 Inspector Name: SCHURE, KYM On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 17180
 Name of Operator: CITATION OIL & GAS CORP
 Address: 14077 CUTTEN RD
 City: HOUSTON State: TX Zip: 77069

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schultz, Ron		rschultz@cogc.com	
Adamczyk, Megan		megan.adamczyk@state.co.us	
Quint, Craig		craig.quint@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257040	WELL	SI	02/01/2019	OW	075-09326	DUBOIS 5	PA

General Comment:

Responding to Stakeholder (landowner) complaint received by ECMC N.E. Field Office by telephone contact from landowner. Landowner expressed safety concerns related to open excavation remaining at wellhead after P&A performed on 4/26/2022. The well has been cut and capped at wellhead. Reference: Rule 1004 Series - requiring excavation backfilled after approval from ECMC Environmental Group and ECMC Flowline Group within (3) three months from date of P&A.
 Contact ECMC Environmental Group for directives
 Contact ECMC Flowline Group for directives.

Inspected Facilities

Facility ID: 257040 Type: WELL API Number: 075-09326 Status: SI Insp. Status: PA

Complaint

Comment: [Please read comments on front page of this FIR for explanation of complaint.](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Stakeholder (landowner) complaint response	schureky	05/22/2024