

**Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC**

**Location Name: PRONGHORN-65N61W 9SWNW**

**Loc ID: 332260**

**Inspection: 708201165**



**Exhibit A**



**Exhibit B**

**CA:** This location does not comply with Rule 1004. During this inspection, it was observed that the reclaimed areas have desirable vegetation throughout, however, there are areas of nonuniform vegetation cover resulting in bare soils. Additional reclamation activities are required. Refer to attached inspection photos. Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

**CA Resolution:** Operator has reported that the location has been appropriately mowed to address any weeds and undesirable vegetation. It has also been noted that the area has been seeded, and straw crimped to provide stabilization and promote more uniform future growth. Bare areas have also been addressed. Location currently complies with Rule 1004.