

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403766518

Date Received:
05/21/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 708301916
Inspection Date: 03/26/2024 FIR Submit Date: 03/30/2024 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335394

Location Name: PUCKETT-66S96W Number: 32SWNW County: _____
Qtrqtr: SWN Sec: 32 Twp: 6S Range: 96W Meridian: 6
W
Latitude: 39.483118 Longitude: -108.138667

FACILITY - API Number: 05-045-00 Facility ID: 335394

Facility Name: PUCKETT-66S96W Number: 32SWNW
Qtrqtr: SWN Sec: 32 Twp: 6S Range: 96W Meridian: 6
W
Latitude: 39.483118 Longitude: -108.138667

CORRECTIVE ACTIONS:

1 CA# 193761

Corrective Action: Secure load line to comply with Rule 608.e. Date: 04/04/2024

Response: CA COMPLETED Date of Completion: 04/10/2024

Operator Comment: Loadline is now plugged. Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

2 CA# 193762

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 04/30/2024

Response: CA COMPLETED

Date of Completion: 05/20/2024

Operator Comment: Location and access road have been bladed/graded to remove rutting. Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA #193761: Loadline is now plugged. Corrective Action complete.
CA #193762: Location and access road have been bladed/graded to remove rutting. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 5/21/2024 11:47:21 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403766518	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files