

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403784278

Date Received:

05/22/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708301941

Inspection Date: 03/28/2024

FIR Submit Date: 04/01/2024

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334871

Location Name: WILLIAMS-67S96W Number: 1NWNW County: _____

Qtrqtr: NWN Sec: 1 Twp: 7S Range: 96W Meridian: 6
W

Latitude: 39.472070 Longitude: -108.064900

FACILITY - API Number: 05-045- -00 Facility ID: 334871

Facility Name: WILLIAMS-67S96W Number: 1NWNW

Qtrqtr: NWN Sec: 1 Twp: 7S Range: 96W Meridian: 6
W

Latitude: 39.472070 Longitude: -108.064900

CORRECTIVE ACTIONS:

1 ☒ CA# 193783

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 05/01/2024

Response: CA COMPLETED

Date of Completion: 04/04/2024

Rill on east end of the pad has been repaired. Location entrance has been further stabilized to prevent tracking. Corrective Action complete.

Operator _____
Comment:

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Rill on east end of the pad has been repaired. Location entrance has been further stabilized to prevent tracking.
Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 5/22/2024 2:03:48 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403784278	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files