

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403784072

Date Received:  
05/08/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 6 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Newville, Toni</u>		<u>toni_newville@oxy.com</u>
<u>ERIN JOSEPH</u>	<u>970-515-1169</u>	<u>ECMCInspections@Oxy.com</u>
<u>ECMC</u>		<u>dnr_cogccenforcement@state.co.us</u>
<u>Sanchez, Chris</u>		<u>chris.sanchez@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 713600952  
Inspection Date: 04/16/2024 FIR Submit Date: 04/18/2024 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: OXY USA INC Company Number: 66561  
Address: PO BOX 173779  
City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 324493

Location Name: GARCIA-627S70W Number: 35NESE County: HUERFANO  
Qtrqr: NESE Sec: 35 Twp: 27S Range: 70W Meridian: 6  
Latitude: 37.655840 Longitude: -105.180780

FACILITY - API Number: 05-055-00 Facility ID: 211777

Facility Name: GARCIA (EPA) Number: 1-WD  
Qtrqr: NESE Sec: 35 Twp: 27S Range: 70W Meridian: 6  
Latitude: 37.655840 Longitude: -105.180780

CORRECTIVE ACTIONS:

3  CA# 194377

Corrective Action: Comply with the fencing requirements per the 1002a rules Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 04/30/2024

SEE ATTACHED PHOTOS OF REPAIRED FENCING

Operator  
Comment:

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

5  CA# 194379

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 04/30/2024

Operator  
Comment: WATTLES HAVE BEEN REPLACED SEE ATTACHED PHOTOS

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

6  CA# 194480

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o  
Comply with Rule 902.b. for pollution prevention.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 04/30/2024

Operator  
Comment: SEE REPAIRED BERMS IN PHOTOS ATTACHED

ECMC Decision: **Not Approved**

ECMC  
Representative: The berm around the tank must be compacted to be impermeable. The berm should contain a spill to the area of  
the tank and not be directed toward the southwest portion of the location near the perennial stream. Based on  
photos provided, secondary containment is not sufficient.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: ERIN JOSEPH

Signed: \_\_\_\_\_

Title: SR REGULATORY ADVISOR

Date: 5/8/2024 2:24:05 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
403784072	FIR RESOLUTION SUBMITTED
403784083	REWORKED BERMS
403784085	WATTLES REPLACED
403784088	PERIMETER FENCE REPAIRED

Total Attach: 4 Files