

Inspection Photos

May 24th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306938

Inspection Document #: 714000793

La Plata County, CO

Township: SESW 18 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Litton Federal 1
Location ID: 306938



5/24/24
+37.297539,-107.682169
262° W



5/24/24
+37.297452,-107.682245
349° NW

LITTON FEDERAL #2
SIMCOE LLC

API #: 06-067-09079	DWR #: 70738-F
LEASE #: COCT126	CA #: COCA9724
SURFACE LOCATION: SESW SEC 18 - T35N - R7W	991' FSL 1335' FWL
BOTTOM HOLE LOCATION: SESW SEC 18 - T35N - R7W	1008' FSL 1339' FWL
LATITUDE: 37.29765336	LONGITUDE: -107.6825349
NEAREST ADDRESS: 7771 CR 502	
CONTROL CENTER 24 HR. PHONE #: 970-247-6916	
EMERGENCY CONTACT #: 911	

Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Litton Federal 1
Location ID: 306938



Photo 2. View of impacted surface material at the well head.

Inspection Photos
Location Name: Litton Federal 1
Location ID: 306938



5/24/24
+37.297452, -107.682245
217° SW

Photo 3. View of the southern interim reclamation area facing south west.

Inspection Photos
Location Name: Litton Federal 1
Location ID: 306938



Photo 4. Reference area comprised of smooth brome, juniper and gambel oak.